


T. 144 R. 29 M. 5TH Coordinates: X _____ Y _____
C.N. 116 Corner common to sections 15



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1926
Original monument 1x36" 1/2" w/ brass ^C N 1/4 1/2 S 15
1926

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Poplar</u>	<u>Poplar</u>	
<u>5"</u>	<u>16"</u>	
<u>S86E</u>	<u>N4W</u>	
<u>42 LKS</u>	<u>21 LKS</u>	

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1992
Doc. # 264942
found GLO monument in good condition.
6" W. OAK N14W 29.28';
8" Tamarack S24W 112.88';
10" W. OAK S65E 22.36'