


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

N 1/4 4 Corner common to sections 4 and 33/145/30



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor 1/4 S4
 Original monument Set 1"x 36" iron pipe w/brass cap 1930
S 89°31' W, 1.34 Chains(88.44') from SW Sec. 34

Original Evidence Found

Year of search 1964 by Okerman
 Monument found GLO iron
USFS Book 1, page 6

Bearing Trees

Species	<u>Balsam</u>	<u>White Pine</u>
Diameter	<u>12"</u>	<u>10"</u>
Bearing	<u>S 35° E</u>	<u>S 46 3/4° W</u>
Distance	<u>42 links</u>	<u>21 links</u>

Original Bearing Trees Found

Species	<u>Balsam Stump</u>	<u>W. Pine</u>
Diameter	<u>decayed</u>	<u>13"</u>
Bearing	<u>S 35° E</u>	<u>S 47° W</u>
Distance	<u>27.7'</u>	<u>13.9'</u>

Subsequent Corner Restoration

Year surveyed 4/1964 By W.H. Okerman, LS 6807
 Location filed: USFS Book 1, page 6
 Monument: Found 1" GLO iron pipe with brass cap and original witnesses and marked new witnesses as follows.

Evidence of Subsequent Corner Restoration

Year of search 5/1991 By G. Brama, USFS
 Location filed: USFS Book 1, page 6
 Monument: Found brass capped pipe up 6" and witnesses as follow.
16" W. Pine, S 47° W, 13.9'(1930)
13" Maple, S 22° E, 45.2'(1964)
12" Oak, N 18° W, 13.5'(1964)

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Oak</u>
Diameter	<u>10"</u>	<u>12"</u>
Bearing	<u>S 21 1/2° E</u>	<u>S 17 1/2° W</u>
Distance	<u>45.2'</u>	<u>13.5'</u>

Bearing Trees, Reference Objects

Species	<u>Yellow Birch</u>	<u>Red Oak</u>	<u>Steel Sign</u>
Diameter	<u>15"</u>	<u>10"</u>	<u>Post</u>
Bearing	<u>S 69° E</u>	<u>S 2° E</u>	<u>North</u>
Distance	<u>25.85'</u>	<u>60.90'</u>	<u>3'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Index No. A11

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 4 Corner common to sections 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1930 1/4 54
Original monument 1x36" W.P. w/ brass cap
S 89°31' W 1.34 CH from 33/34
1930

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Balsam White _____
Diameter 12" 10" _____
Bearing S 35 E S 46 3/4 W _____
Distance 42 LKS 21 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1964 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species W. Pine Maple Oak _____
Diameter 13" 10" 12" _____
Bearing S 46 3/4 W S 21 1/2 E N 17 1/2 W _____
Distance 13.90' 45.20' 13.50' _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Bill Okerman - 1964

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____