


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

NE 4 Corner common to sections 3, 4 and 34/145/30



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument C.C. Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____

Historical Society Notes

Bearing Trees

Species	Elm	Lynn
Diameter	<u>12"</u>	<u>12"</u>
Bearing	<u>S 40° W</u>	<u>S 12° E</u>
Distance	<u>45 links</u>	<u>23 links</u>

Original Bearing Trees Found

Species	Basswood
Diameter	<u>Stump</u>
Bearing	<u>S 12° E</u>
Distance	<u>23 links</u>

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, US Surveyor
Location filed: Minnesota Historical Soc., Notes T145N R30W
Monument: Set 2"x 36" iron pipe with brass cap S34
from original witness, S 89°31' W, 1.42 chains S4 | S3
(93.72') from S. 1/4, Sec. 34 and marked new T144N R30W
witnesses as follows. CC
1930

Bearing Trees, Reference Objects

Species	Spruce	Elm
Diameter	<u>5"</u>	<u>4"</u>
Bearing	<u>S 30 1/2° E</u>	<u>S 39 1/2° W</u>
Distance	<u>35 links</u>	<u>30 links</u>

Evidence of Subsequent Corner Restoration

Year of search 4/1964 By W.H. Okerman, LS 6807
Location filed: USFS Book 1, page 4
Monument: Found GLO brass capped pipe and witnesses as follow.
Spruce stump, S 33° E, 23.1'(1930)
8" Elm, S 40° W, 19.8'(1930)

Bearing Trees, Reference Objects

Species	Elm	Maple	Twin Elm
Diameter	<u>6"</u>	<u>6"</u>	<u>8"</u>
Bearing	<u>S 22° W</u>	<u>S 41° E</u>	<u>N 14° W</u>
Distance	<u>19.8'</u>	<u>41.15'</u>	<u>4.3'</u>

Subsequent Corner Restoration

Year surveyed 4/1991 By G. Brama, USFS
Location filed: USFS Book 1, page 4
Monument: Found GLO iron with brass cap up 6", 30' S. of F.S. 2932 and witnesses as follows.
10" Maple, S 41° E, 41.15'(1964)
13" Ash, S 16° W, 24.75' scribed
20" Yellow Birch, S 70° W, 102.4' scribed
8" Ash, S 50° W, 36.47' scribed
Steel Sign Post, South, 3'


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. A13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
NE 4 Corner common to sections 3, 4



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument C.C. Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Elm</u>	<u>42°N</u>	
<u>12"</u>	<u>12"</u>	
<u>S40W</u>	<u>S12E</u>	
<u>45 LKS</u>	<u>23 LKS</u>	

Species	Bearing	Trees
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument Set 2x36" I.P. w/ brass cap from stump of SE cor.
S89-31w 1.42 CH from S1/4 34 T145N R30W

Evidence of Subsequent Corner Restoration
Year of search 1964 By William Okerman
Found GLO monument in good condition.

534
54153
T145N R30W
Bearing Trees, Reference Objects CC 1930

Species	Bearing	Distance
<u>SPRUCE</u>	<u>530 1/2 E</u>	<u>35 LKS</u>
<u>Elm</u>	<u>539 1/2 W</u>	<u>30 LKS</u>

Bearing Trees, Reference Objects

Species	Bearing	Distance
<u>Elm</u>	<u>6"</u>	<u>19.80'</u>
<u>Maple</u>	<u>6"</u>	<u>41.15'</u>
<u>Twin Elm</u>	<u>8"</u>	<u>4.30'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1964

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____