


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

E 1/16 Corner common to sections 1 and 31/145/29



EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor E 1/16
 Original monument Set 2"x 36" iron pipe w/brass cap S 1
S 89°39' E, 5.93 Chains(391.38') from SW Sec. 31 1930

Original Evidence Found

Year of search 1936 by CCC
 Monument found GLO iron
 Form 874-9

Bearing Trees

Species	<u>Poplar</u>	<u>Poplar</u>	_____
Diameter	<u>10"</u>	<u>10"</u>	_____
Bearing	<u>S 32 3/4° E</u>	<u>S 1 1/4° W</u>	_____
Distance	<u>72 links</u>	<u>59 links</u>	_____

Original Bearing Trees Found

Species	<u>Aspen</u>	<u>Aspen</u>	_____
Diameter	<u>10"</u>	<u>11"</u>	_____
Bearing	<u>S 35°30' E</u>	<u>S 20° E</u>	_____
Distance	<u>73.2 links</u>	<u>61 links</u>	_____

Subsequent Corner Restoration

Year surveyed 12/1936 By L. Folsom, CCC
 Location filed: Form 874-9
 Monument: Found metal pipe up 4" in good condition and GLO witnesses.

Evidence of Subsequent Corner Restoration

Year of search 11/1965 By J. Ekstrom, USFS
 Location filed: USFS Book 1, page 8
 Monument: Found 1" GLO iron pipe with brass cap and original witnesses and marked new witnesses as follows. 4" Cedar Post, N 80° E, 2.0' 54-4 sign

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Aspen</u>	<u>Aspen</u>	<u>Oak</u>	<u>Oak</u>
Diameter	<u>16"(1930)</u>	<u>fallen(1930)</u>	<u>8"</u>	<u>4"</u>
Bearing	<u>S 32° E</u>	<u>S 1° W</u>	<u>S 4° W</u>	<u>S 15° E</u>
Distance	<u>47.52'</u>	<u>38.94'</u>	<u>53.0'</u>	<u>48.3'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Index No. A25

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/16 Corner common to sections 1



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1930
Original monument 2x36" 1/2" w/brass E 1/16
C&P 51
1930

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Poplar Poplar _____
Diameter 10" 10" _____
Bearing S32 3/4 E S1 1/4 W _____
Distance 72 LKS 59 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1965 By William Okerman
Location filed _____
Monument Found GLO monument in good
condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Oak Oak Cedar Post
Diameter 8" 4" 4x4x60"
Bearing S4W S1SE N80E
Distance 53.00' 48.30' 2.00'

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE Bill Okerman - 1965

Remonumentation certificate prepared _____ By _____