


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
SMC Corner common to sections 1
on W 1/16 line



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor
Original monument 12" Elm scribed SMC on the N. face
and S1 on the S. face

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species Ash Elm
Diameter 13" 10"
Bearing S 27° E S 0°45' E
Distance 139 links 153 links

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 9/1983 By C.R. Krause, USFS
Location filed: USFS Book 2, page 67
Monument: Position falls in lake
Found remains of witnesses and White Oak line tree as noted
South 7.99 chains(527.3')

Evidence of Subsequent Corner Restoration

Year of search 9/1983 By M.C. Hayes, USFS
Location filed: USFS Book 2, page 67 T144N R30W
Monument: Set USFS 2.5" ODIP with brass cap WC
as witness, 9.26' S. of corner position in lake, SMC
up 0.3', 660' N. of FR 2135 and witnessed as S1
follows. 1983 9.26 FT
RLS No 14677

Bearing Trees, Reference Objects

Species Ash(1930) Elm(1930)
Diameter roots Stump
Bearing S 27° E S 1° E
Distance 91.7' 101.0'

Bearing Trees, Reference Objects

Species Ash Ash Ash Steel Sign
Diameter 5" 5" 6" Post
Bearing S 85° E S 63° E S 28° E North
Distance 30.62' 69.43' 93.05' 2.55'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

