


Index No. A.6-20.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

SMC Corner common to sections 2

on E 1/16 line



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor SMC  
Original monument Set 1"x 36" iron pipe w/brass cap E  
S 1/2  
E  
1930

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>8"</u>	<u>12"</u>
Bearing	<u>S 52 1/2° E</u>	<u>S 64 1/2° W</u>
Distance	<u>50 links</u>	<u>50 links</u>

Original Evidence Found

Year of search 1985 by USFS  
 Monument found GLO brass cap  
USFS Book 2, page 75

Original Bearing Trees Found

Species	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>11"</u>	<u>14"</u>
Bearing	<u>S 58° E</u>	<u>S 61° W</u>
Distance	<u>33.0'</u>	<u>33.65'</u>

Subsequent Corner Restoration

Year surveyed 10/1985 By C.R. Krause, USFS  
 Location filed: USFS Book 2, page 75  
 Monument: Found GLO iron pipe with brass cap up 30", leaning S. against bank, straighten and witnessed. 661' N 1° E from FR 2135.

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Ash</u>
Diameter	<u>8"</u>	<u>7"</u>
Bearing	<u>S 21° E</u>	<u>S 60° E</u>
Distance	<u>66.45'</u>	<u>18.20'</u>

Evidence of Subsequent Corner Restoration

Year of search 6/1986 By G. Brama, USFS  
 Location filed: USFS Book 2, page 75  
 Monument: Reset GLO pipe with brass cap up 6", braced with 6' sign post on N. side and witnessed as follows.

Bearing Trees, Reference Objects

Species	<u>Steel Sign</u>
Diameter	<u>Post</u>
Bearing	<u>South</u>
Distance	<u>4.1'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

