


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 3 Corner common to sections 2, 3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species Balsam Yellow Birch
Diameter 5" 10"
Bearing N 89° E S 58° E
Distance 6 links 44 links

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Historical Society, notes 1/4
Monument: Set 1"x36" iron pipe with brass cap S3|S2
at proportionate position and witnesses as follows. 1930

Evidence of Subsequent Corner Restoration

Year of search 11/1931 By E.L. Victor, Estimator CCC
Location filed: Form 874-9
Monument: Found iron pipe up 11" in good condition and witnesses as follow.

Bearing Trees, Reference Objects

Species Cedar Cedar
Diameter 7" 9"
Bearing N 59 1/4° E N 68 1/4° W
Distance 76 links 43 links

Bearing Trees, Reference Objects

Species Cedar Cedar
Diameter 8"(1930) 6"(1930)
Bearing N 64° W N 65° E
Distance 45 links 76 links

Subsequent Corner Restoration

Year surveyed 3/1981 By G. Brama, USFS
Location filed: USFS Book 1, page 40
Monument: Found GLO brass capped pipe up 1.5' in good condition and witnesses as follow.
17" Cedar, N 59° E, 50.29'(1930) scar visible
16" Cedar, N 68° W, 28.4'(1930) rescribed
11" Ash, S 2° E, 39.1' scribed

9/1982, G.H. Stevenson, LS 12684
Certificate of Location
Found GLO brass capped iron pipe and witnesses from USFS.

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed: _____
Monument: _____

6/1986, G. Brama, USFS
USFS Book 1, page 40
Found corner and set posts as follow.
Steel Sign Post, East, no distance
Steel Sign Post, South, no distance

Index No. C17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
E1143 Corner common to sections 2,3



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Balsam 1/2 Birch
Diameter 5" 10"
Bearing N89E S58E
Distance 6LKS 44LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of state
Monument Set 1x36" 1/2 w/brass cap 114
53/52
1930

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Cedar Cedar
Diameter 7" 9"
Bearing N59 1/4 E N68 1/4 W
Distance 76LKS 43LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Garry Stevenson - 1982
Doc. # 264948
Found GLO monument and BT's in
good condition.
11" Ash S2E 39.1'.

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____