


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

C 1/4 Corner common to sections 2



EXISTING SURVEYS

Original Government Survey

Year surveyed 6/1930, H.D. Craig, US Surveyor C 1/4 S2
Original monument Set 1"x36" iron with brass cap 1930

Original Evidence Found

Year of search _____ by _____
Monument found _____

Resurvey Notes, MN Historical Society

Bearing Trees

Species	<u>White Pine</u>	<u>White Pine</u>	_____	_____
Diameter	<u>12"</u>	<u>14"</u>	_____	_____
Bearing	<u>N 74° E</u>	<u>N 24° W</u>	_____	_____
Distance	<u>22 links</u>	<u>8 links</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 11/1934 By D.J. Sutton, CCC Compassman
Location filed: USFS Form 874-9
Monument: Brass cap 1" iron pipe up 12", placed metal location poster on the NE Pine.

Evidence of Subsequent Corner Restoration

Year of search 3/1981 By C.R. Krause, USFS
Location filed: USFS Book 2, page 77
Monument: Found GLO iron pipe with brass cap up 12", and witnessed as follows.
Steel Sign Post, North, 4.5' 54-2 and 54-4 signs
Steel Sign Post, East, 4.5' 54-2 and 54-4 signs

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>White Pine</u>	_____	_____
Diameter	<u>11"(1930)</u>	<u>12"(1930)</u>	_____	_____
Bearing	<u>N 73°45' E</u>	<u>N 22°45' W</u>	_____	_____
Distance	<u>22 links</u>	<u>8 links</u>	_____	_____

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>White Pine</u>	<u>Norway Pine</u>	<u>Norway Pine</u>
Diameter	<u>17"(1930)</u>	<u>19"(1930)</u>	<u>23"</u>	<u>19"</u>
Bearing	<u>N 74° E</u>	<u>N 24° W</u>	<u>S 5° E</u>	<u>N 50° E</u>
Distance	<u>14.5'</u>	<u>5.3'</u>	<u>132.68'</u>	<u>102.58'</u>

Subsequent Corner Restoration

Year surveyed 6/1986 By USFS
Location filed: USFS Book 2, page 77
Monument:
Line to standard goes E. from corner.


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. C19

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
C114 Corner common to sections 2



EXISTING SURVEYS

Original Government Survey

Year surveyed 1930
Original monument 1x36" IR. w/brass cap C114 52
1930

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species W. Pine W. Pine
Diameter 12" 14"
Bearing N74E N24W
Distance 22 LKS 8 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264949
Found GLO monument and BT's in good condition.
23" N. Pine S5E 132.68'
19" N. Pine N50E 102.58'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____