


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

E 1/4 2 Corner common to sections 1, 2



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1900 by COE
Monument found _____

Leech Lake Reservoir Map

Bearing Trees

Species	<u>White Pine</u>	<u>White Pine</u>	_____
Diameter	<u>36"</u>	<u>24"</u>	_____
Bearing	<u>S 85° W</u>	<u>N 16 1/2° E</u>	_____
Distance	<u>590 links</u>	<u>750 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1900 By H. Dunaway, COE
Location filed: Leech Lake Reservoir Map
Monument:
Map indicates a known corner.

Evidence of Subsequent Corner Restoration

Year of search 6/1930 By H.D. Craig, US Surveyor
Location filed: Resurvey Notes, pg 52, MN Hist. Soc. 1/4
Monument: Set 1"x36" iron pipe with brass cap S2 | S1
up 6", from remains of original witnesses 1930
26" White Pine stump, N 17 1/2° E, 750 links(495')
36" White Pine stump, S 86°39' W, 590 links(389.4')
and marked new witnesses as follows.

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Birch</u>	_____
Diameter	<u>16"</u>	<u>12"</u>	_____
Bearing	<u>N 40°22' E</u>	<u>S 86°36' W</u>	_____
Distance	<u>751 links</u>	<u>545 links</u>	_____

Subsequent Corner Restoration

Year surveyed 12/1936 By L. Fulson, CCC
Location filed: Form 874-9
Monument: Found Metal pipe
in good condition and notes witnesses as follows.
16" Norway Pine, N 39° E, 7.47 chains(493.02')

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____


10/1985, C.R. Krause, USFS
USFS Book 2, page 73
Found GLO iron pipe with brass cap, up 12", in grass swamp,
did not look for old witnesses and witnessed as follows.
13" Twin White Oak, S 89° E, 98.5' FSLP

3/1994, R. Main, USFS
USFS Book 2, page 73
Found GLO iron pipe with brass cap, up 4" above ice in marsh
grass, 35' SW of Sucker Creek, 100' E. of highland, witnesses.
11" White Oak, N 48° W, 167.40' marked 1/4 S2 BT
14" White Oak, N 88° W, 97.80' marked 1/4 S2 BT
Steel Sign Post, South, 4.0'
Steel Sign Post, East, 4.3'

Index No. C 21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 R Corner common to sections 1, 2



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species W. Pine W. Pine
Diameter 36" 24"
Bearing S 85W N 16 1/2 E
Distance 590 LKS 750 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument End Stamps of both B.T.S. Set 1x36" L.P. w/ Brass cap

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species N. Pine Birch
Diameter 16" 12"
Bearing N 40-22 E S 86-36 W
Distance 751 LKS 545 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____