


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

C 1/4 Corner common to sections 11



EXISTING SURVEYS

Original Government Survey

Year surveyed 6/1930, H.D. Craig, US Surveyor C 1/4 S11
Original monument Set 1"x36" iron with brass cap 1930

Original Evidence Found

Year of search 1980 by Krause
Monument found pipe
USFS Book 3, page 5

Resurvey Notes, MN Historical Society

Bearing Trees

Species	<u>Birch</u>	<u>Norway Pine</u>	_____
Diameter	<u>7"</u>	<u>12"</u>	_____
Bearing	<u>S 56 1/2° E</u>	<u>N 89° W</u>	_____
Distance	<u>187 links</u>	<u>206 links</u>	_____

Original Bearing Trees Found

Species	<u>Birch</u>	<u>Red Pine</u>	_____
Diameter	<u>11"</u>	<u>Windfall</u>	_____
Bearing	<u>S 56° E</u>	<u>N 89° W</u>	_____
Distance	<u>123.4'</u>	<u>136.0'</u>	_____

Subsequent Corner Restoration

Year surveyed 7/1980 By C.R. Krause, USFS
Location filed: USFS Book 3, page 5
Monument: iron pipe
placed metal location poster on the following.

Evidence of Subsequent Corner Restoration

Year of search 3/1981 By G. Brama, USFS
Location filed: USFS Book 3, page 5
Monument: Found iron pipe
up 5", and witnessed as follows.
Steel Sign Post, East, 3.0'
Steel Sign Post, West, 2.95'

Bearing Trees, Reference Objects

Species	<u>White Spruce</u>	_____	_____
Diameter	<u>10"</u>	_____	_____
Bearing	<u>N 48° W</u>	_____	_____
Distance	<u>8'</u>	_____	_____

Bearing Trees, Reference Objects

Species	<u>Birch</u>	<u>Jack Pine</u>	<u>Jack Pine</u>	<u>Spruce</u>
Diameter	<u>11"(1930)</u>	<u>10"</u>	<u>10"</u>	<u>9"</u>
Bearing	<u>S 56° E</u>	<u>S 82° W</u>	<u>N 47° W</u>	<u>N 49° E</u>
Distance	<u>123.4'</u>	<u>14.24'</u>	<u>93.88'</u>	<u>34.0'</u>

Subsequent Corner Restoration

Year surveyed 12/2002 By R. Main, USFS
Location filed: USFS Book 3, page 5
Monument: Found iron
blowdown around corner, locates with GPS and witnesses.
9" Spruce, N 49° E, 34.0'(1981) standing dead
10" Jack Pine, S 82° W, 14.24'(1981) tall snag
13" Jack Pine, N 47° W, 93.88'(1981)


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. G 19

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
C14 Corner common to sections 11



EXISTING SURVEYS

Original Government Survey

Year surveyed 1930
Original monument 1x36" I.P.W. Brass
cup

clly 511
1930

Bearing Trees
Species Birch N. Pine
Diameter 7" 12"
Bearing S56 1/2 E N89W
Distance 187 LKS 206 LKS

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gary Stevenson - 1982
Doc. # 264951
Found GLO monument in good condition.
10" J. Pine N47W 93.88';
10" J. Pine S82W 14.24';
9" Spruce N49E 34.0';
12" Birch S57E 123.4' (1930 BT).

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____