


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

S 1/16 Corner common to sections 10, 11



EXISTING SURVEYS

Original Government Survey

Year surveyed 3/1981, G. Brama, USFS T144N R30W
 Original monument Set 2.5"x 30" alum. pipe S1/16 S10|S11
 with aluminum cap. Up 6" 1981
 RLS 14677

Original Evidence Found

Year of search _____ by _____
 Monument found _____

Bearing Trees

Species	Cedar	Ash	Ash	Steel Sign
Diameter	8"	5"	9"	Post
Bearing	N 76° E	S 56° W	N 72° W	North
Distance	79.93'	40.13'	25.08'	2.9'

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 12/2002 By R. Main, USFS
 Location filed: USFS Book 3, page 6
 Monument: Found corner in good condition, 40' N. of Forest Rd. and located with GPS.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Bearing Trees, Reference Objects

Species	Steel Sign	_____	_____	_____
Diameter	Post	_____	_____	_____
Bearing	West	_____	_____	_____
Distance	3.0'	_____	_____	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Index No. H 17

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
5116 Corner common to sections 10, 11



EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

Bearing Trees

Species _____

Diameter _____

Bearing _____

Distance _____

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1981 By USFS

Location filed _____

Monument Set 2 1/2 x 30" aluminum post w/aluminum top

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed _____

Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

1986 Certificate - Ken Whitehorn

Doc. # 290151

Set 2 1/2 x 30" aluminum pipe with 3" stamped aluminum tablet up to

9" Ash N72W 25.08';

8" Cedar N76E 79.93';

5" Ash S56W 40.13'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____