


Index No. P.0-16.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

C.E. 1/16 Corner common to sections 22



EXISTING SURVEYS

Original Government Survey

Year surveyed 6/1930, H.D. Craig, US Surveyor E 1/16

Original monument Set 1"x 36" iron pipe w/brass cap ^c S22 ^c 1930

Original Evidence Found

Year of search _____ by _____

Monument found _____

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>
Diameter	<u>10"</u>	<u>10"</u>
Bearing	<u>N 79 1/2° E</u>	<u>S 23 3/4° E</u>
Distance	<u>81 links</u>	<u>144 links</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 10/1934 By B. Leet, Compassman, CCC

Location filed: Form 874-9

Monument: Found Brass capped pipe up 10" in good condition and the following witnesses.

Evidence of Subsequent Corner Restoration

Year of search 4/1977 By C.R. Krause, USFS

Location filed: USFS Book 1, page 73

Monument: Found iron pipe with brass cap up 18" in good condition, and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Cedar</u>	_____
Diameter	<u>8"</u>	<u>7"</u>	_____
Bearing	<u>N 78°45' E</u>	<u>S 15°45' W</u>	_____
Distance	<u>80 1/2 links</u>	<u>143 3/4 links</u>	_____

Bearing Trees, Reference Objects

Species	<u>Cedar</u>	<u>Cedar</u>	<u>Cedar</u>	_____
Diameter	<u>16"(1930)</u>	<u>14"(1930)</u>	<u>5"(FSLP)</u>	_____
Bearing	<u>N 80° E</u>	<u>S 24° E</u>	<u>S 20° W</u>	_____
Distance	<u>53.5'</u>	<u>95.0'</u>	<u>5.0'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Location filed: _____

Monument: _____

