


Index No. P.0-24.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

CE 1/16 Corner common to sections 24



EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor E1/16
 Original monument Set 1"x 36" iron pipe w/brass cap S24
 1930

Original Evidence Found

Year of search 1991 by USFS
 Monument found GLO iron
USFS Book 3, page 3

Bearing Trees

Species	<u>Cedar</u>	<u>Cedar</u>	_____
Diameter	<u>12"</u>	<u>8"</u>	_____
Bearing	<u>S 81 1/4° W</u>	<u>N 31 1/4° W</u>	_____
Distance	<u>46 links</u>	<u>34 links</u>	_____

Original Bearing Trees Found

Species	<u>Cedar stump</u>	_____	_____
Diameter	<u>rotted</u>	_____	_____
Bearing	<u>S 81° W</u>	_____	_____
Distance	<u>30.4'</u>	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1991 By C.R. Krause, USFS
 Location filed: USFS Book 3, page 3
 Monument: Found GLO iron with brass cap up 12" and witness remains, make new witnesses as follow.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
 Location filed: _____
 Monument: _____

Bearing Trees, Reference Objects

Species	<u>Yellow Birch</u>	<u>Maple</u>	<u>Cedar</u>	<u>Steel Sign</u>
Diameter	<u>13"</u>	<u>12"</u>	<u>17"</u>	<u>Post</u>
Bearing	<u>N 48° W</u>	<u>N 51° E</u>	<u>S 25° E</u>	<u>North</u>
Distance	<u>57.1'</u>	<u>42.6'</u>	<u>18.95'</u>	<u>3'</u>

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed: _____
 Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

