


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 29 Corner common to sections 20, 29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>White Birch</u>
Diameter	<u>10"</u>	<u>8"</u>
Bearing	<u>S 5° E</u>	<u>N 42° W</u>
Distance	<u>20 links</u>	<u>185 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1930 By H.D. Craig, US Surveyor
Location filed: Minn. Hist. Society, notes 1/4 S20
Monument: Set 1"x36" iron pipe with brass cap S29
up 6", at proportionate position and marked 1930
new witnesses as follows.

Evidence of Subsequent Corner Restoration

Year of search 9/1934 By D.J. Sutton, Compassman CCC
Location filed: Form 874-9
Monument: Found 1" brass capped pipe
up 12" in good condition, placed a metal location poster on the
SW witness tree and notes witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Birch</u>
Diameter	<u>3"</u>	<u>6"</u>
Bearing	<u>S 12° W</u>	<u>N 70° W</u>
Distance	<u>7 links</u>	<u>106 links</u>

Bearing Trees, Reference Objects

Species	<u>White Birch</u>	<u>Aspen</u>
Diameter	<u>6"(1930)</u>	<u>4"</u>
Bearing	<u>N 71 1/4° W</u>	<u>S 49° W</u>
Distance	<u>107 links</u>	<u>16 1/4 links</u>

Subsequent Corner Restoration

Year surveyed 3/1975 By C.R. Krause, USFS
Location filed: USFS Book 1, page 25
Monument: Found GLO iron pipe with brass cap
up 12", 1270' N. of road and witnesses as follow.
7" Elm, S 12° W, 4.6'(1930) rescribe BT
10" Birch snag, N 70° W, 70.0'(1930) scribe rotted
8" White Oak, S 25° E, 22.35' scribed
7" Maple, N 50° E, 28.0' scribed
6" Elm, N 15° W, 31.3' scribed
10" White Spruce, South, 1260' FSLP


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. R7

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 574 Coordinates: X _____ Y _____
N1/4 29 Corner common to sections 20, 29



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species Aspen W. Birch
Diameter 10" 8"
Bearing S5E N42W
Distance 20 LKS 185 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec 2 F State
Monument Set 1x36" i.p. witness cap 1/4 Sec 20
529
1930

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species Elm Birch
Diameter 3" 6"
Bearing S113/4W N70 1/4W
Distance 7 LKS 106 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1975 - Filed in 1980
Doc. # 258587
Found GLO monument in good condition
8" W. Oak S25E 22.35';
7" Maple N50E 28.00';
6" Elm N15W 31.30'

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____