


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____

C.E. 1/16 Corner common to sections 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 6/1930, H.D. Craig, US Surveyor E 1/16
 Original monument Set 1"x 36" iron pipe w/brass cap C—S28—C
 Corner at W. edge of swamp. 1930

Original Evidence Found

Year of search _____ by _____
 Monument found _____

Bearing Trees

Species	<u>White Pine</u>	<u>White Pine</u>	_____	_____
Diameter	<u>16"</u>	<u>20"</u>	_____	_____
Bearing	<u>N 14 1/4° E</u>	<u>S 61° E</u>	_____	_____
Distance	<u>54 links</u>	<u>106 links</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 11/1931 By P. Zeleagraff, Estimator CCC
 Location filed: Form 874-9
 Monument: Found Brass capped I. pipe up 10" in good condition and the following witnesses.

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>White Pine</u>	_____	_____
Diameter	<u>15"</u>	<u>20"</u>	_____	_____
Bearing	<u>N 7° E</u>	<u>S 62° E</u>	_____	_____
Distance	<u>36'</u>	<u>69'</u>	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 3/1975 By C.R. Krause, USFS
 Location filed: USFS Book 1, page 62
 Monument: Found iron pipe with brass cap top 12" is bent flush to ground, on back slope of road. Straighten iron and reset, down 6" and notes witnesses as follow.
 24" White Pine, N 14° E, 35.6'(1930) scribe visible
 26" White Pine stump, S 61° E, 70.0'(1930) scribe visible
 Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>Basswood</u>	<u>Cedar Post</u>	_____
Diameter	<u>27"</u>	<u>8"</u>	<u>4"</u>	_____
Bearing	<u>N 16° W</u>	<u>S 14° E</u>	<u>North</u>	_____
Distance	<u>88.4'</u>	<u>47.3'</u>	<u>1.1'</u>	_____

Subsequent Corner Restoration

Year surveyed 5/1986 By C.R. Krause, USFS
 Location filed: USFS Book 1, page 62
 Monument: Found iron pipe with brass cap
 Remove monument prior to rd. const., place pellet in hole.

7/1990, C.R. Krause, USFS
 USFS Book 1, page 62
 Reset GLO iron pipe with brass cap, flush, on north shoulder slope of Cuba Hill Rd. place 3 rocks around cor. witnesses.
 24" White Pine, N 14° E, 35.6'(1930) dead snag
 28" White Pine, N 16° W, 88.4'(1975) scribe visible
 10" Ash, N 18° E, 56.00' scribed CE 1/16 S28 BT
 4" White Oak, N 64° W, 62.15' scribed BT
 Steel Sign Post, North, 3.85' 54-2 and 54-4 signs

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

