


Index No. ✓ 18-19

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC #5 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Species	Bearing	Trees
<u>Birch</u>	<u>Birch</u>	
<u>6"</u>	<u>4"</u>	
<u>S30W</u>	<u>N60W</u>	
<u>6 LKS</u>	<u>2 LKS</u>	

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	Diameter	Bearing	Distance

Subsequent Corner Restoration

Year surveyed 1930 By GLO  
Location filed Sec. of State  
Monument Set 1x36" 1/4" w/brass cap on blazed line  
poss: bly by Army Corp of Engineers in 1900 T144N R30W  
Corp Map shows this corner in place in 1900 526/mc  
high water has washed cor. away 535'  
1930

Species	Bearing	Trees, Reference Objects
<u>Ash</u>	<u>Elm</u>	
<u>12"</u>	<u>6"</u>	
<u>N24 1/2 W</u>	<u>S74W</u>	
<u>7 LKS</u>	<u>63 LKS</u>	

Evidence of Subsequent Corner Restoration

Year of search 1988 By Gary Stevenson  
Corner Certificate - Doc # 363 287

Find GLO Brass Cap monument and both 1930  
BIT'S

Bearing Trees, Reference Objects

Species	Bearing	Trees, Reference Objects
<u>Ash</u>	<u>Basswood</u>	<u>Ash</u>
<u>6"</u>	<u>12"</u>	<u>S70W</u>
<u>N10W</u>	<u>N50W</u>	<u>7"</u>
<u>20.93'</u>	<u>19.38'</u>	<u>16.11'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Certificate - Gary Stevenson - 1988

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_