


T. 144 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/16 Corner common to sections 31, 32



EXISTING SURVEYS

Original Government Survey

Year surveyed 5/1930, H.D. Craig, US Surveyor N1/16
Original monuments Set 1"x 36" iron pipe w/brass cap S31|S32
1930

Original Evidence Found

Year of search 1934 by CCC
Monument found GLO iron
Form 874-9

Bearing Trees

Species Poplar Birch
Diameter 8" 12"
Bearing S 16 1/4° E S 73° W
Distance 48 links 36 links

Original Bearing Trees Found

Species Birch
Diameter 10"(1930)
Bearing S 71°30' W
Distance 36 links

Subsequent Corner Restoration

Year surveyed 10/1934 By D.J. Sutton, Compassman, CCC
Location filed: Form 874-9
Monument: Found 1" iron pipe with brass cap up 6", in good condition and GLO witness.

Evidence of Subsequent Corner Restoration

Year of search 1968 By L. Martinsen, USFS
Location filed: USFS Book 2, page 4, 5680-11
Monument: Found iron with brass cap and witness as follow.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species Aspen
Diameter 16"
Bearing S 16° E
Distance 48 links

Subsequent Corner Restoration

Year surveyed 3/1981 By G. Brama, USFS
Location filed: USFS Book 2, page 4
Monument: Found iron pipe up 6", 450' E. of woods trail, 4"x 4" wood post with FSLP N. 867' and witnesses as follow.
16" Aspen, S 16° E, 31.7'(1930)
White Oak, S 68° E, 85.56' scribed
9" Red Oak, S 8° W, 153.15' scribed
3" Maple, N 20° E, 34.97' scribed X BT
Steel Sign Post, North, 4.9'
Steel Sign Post, South, 2.7'
Steel Sign Post, West, 4.8'
Steel Sign Post, East, 2.8'

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed: _____
Monument: _____

9/1982, G.H. Stevenson, LS 12684
Certificate of Location
Found GLO monument and witnesses.

Index No. W 5

CASS COUNTY LAND CORNER RECORD

T. 144 R. 30 M. 57H Coordinates: X _____ Y _____
N 1/16 Corner common to sections 31, 32



O = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1930
Original monument 1x3/8" 118. w/ brass cap

Original Evidence Found

Year of search _____ By _____
Monument found _____

N 1/16
531/532
1930

Bearing Trees
Species Poplar Birch
Diameter 8" 12"
Bearing S 16 1/4 E S 73 W
Distance 40 LKS 36 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - Gery Stevenson - 1982
Doc. # 264965
Found GLO monument in good condition
3" Maple N 20 E 34.97';
W. Oak S 68 E 85.56";
16" Poplar S 16 E 31.7' (1930 BT);
9" R. Oak S 8 W 153.15'

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____