


T. 144 R. 31 M. 5th Coordinates: X _____ Y _____

E 1/4 2 Corner common to sections 1, 2



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____

Bearing Trees

Species	<u>Jack Pine</u>	<u>Jack Pine</u>	_____
Diameter	<u>8"</u>	<u>12"</u>	_____
Bearing	<u>N 59° E</u>	<u>N 52° W</u>	_____
Distance	<u>20 links</u>	<u>16 links</u>	_____

Original Bearing Trees Found

Species	<u>J. Pine stump</u>	<u>J. Pine stump</u>	_____
Diameter	<u>13"</u>	<u>20"</u>	_____
Bearing	<u>N 56 1/2° E</u>	<u>N 49 1/2° E</u>	_____
Distance	<u>20 links</u>	<u>16 links</u>	_____

Subsequent Corner Restoration

Year surveyed 9/1930 By H.D. Craig, U.S. Surveyor, GLO
Location filed: MN Historical Society, notes page 46 1/4
Monument: Set 1"x 3' iron pipe with brass cap S 2 | S 1
up 6" from remains of original bearing trees and 1930
witnessed as follows.

Evidence of Subsequent Corner Restoration

Year of search 4/1934 By J.A. Gjelhaug, Eng. CCC
Location filed: USFS Form 874-9
Monument: Found 1" brass capped Iron pipe
up 6", notes witnesses as follows.

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Norway Pine</u>	_____
Diameter	<u>23"</u>	<u>18"</u>	_____
Bearing	<u>N 81 1/2° E</u>	<u>N 87° W</u>	_____
Distance	<u>160 links</u>	<u>273 links</u>	_____

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Norway Pine</u>	_____
Diameter	<u>14"</u>	<u>16"</u>	_____
Bearing	<u>N 86° W</u>	<u>N 84° E</u>	_____
Distance	<u>270 links</u>	<u>159 links</u>	_____

Subsequent Corner Restoration

Year surveyed 1/1986 By C. Krause, USFS
Location filed: T144N R31W Field Book 1, page 41
Monument: Found 1" Brass capped iron pipe
up 10", chained south from MC 966.2', distance checks and
witnesses.
Norway Pine stump, N 82° E, 105.6'(1930') rotted stump
18" Norway Pine, N 87° W, 180.2'(1930) 20' snag
14" Norway Pine, N 67° W, 24.60' spike and tag
12" Norway Pine, S 72° W, 18.75' spike and tag
8" Norway Pine, N 31° E, 16.60' spike and tag


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. C21

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5TH Coordinates: X _____ Y _____
E114 2 Corner common to sections 112



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument bst

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species J. Pine J. Pine _____
Diameter 8" 12" _____
Bearing N59E N52W _____
Distance 204Ks 164Ks _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument End Stumps of both B.T.S - set 1436"
1/4
ip. wire brass cap
52/51
1930

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species N. Pine None _____
Diameter 23" 18" _____
Bearing N81 1/2 E N87W _____
Distance 1604Ks 2734Ks _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____