


Index No. G13

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E149 Corner common to sections \_\_\_\_\_



EXISTING SURVEYS

**Original Government Survey**  
 Year surveyed 1875  
 Original monument Post

**Bearing Trees**  
 Species Elm Aspen  
 Diameter 6" 6"  
 Bearing N88E N61W  
 Distance 50LKS 18LKS

**Original Evidence Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Monument found \_\_\_\_\_

**Original Bearing Trees Found**  
 Species \_\_\_\_\_  
 Diameter \_\_\_\_\_  
 Bearing \_\_\_\_\_  
 Distance \_\_\_\_\_

**Subsequent Corner Restoration**  
 Year surveyed 1913 By John Curo  
 Location filed County Survey Record Book "A" P605-611  
 Monument Find old Galv. Bit: 6" OAK OR ELM? N88E  
50 LKS, STUMP 6" ASPEN N61W 18LKS, SET 2" x 48"  
GALV. 1 1/2" W/CAP

**Evidence of Subsequent Corner Restoration**  
 Year of search 1930 By GLO  
 Found 1 1/2" i.p. set by Cass Co. w/Galv. cap & remains  
of NE BIT.

**Bearing Trees, Reference Objects**  
 Species OAK OAK  
 Diameter 27" 10"  
 Bearing S83-49W S36-15E  
 Distance 23.72' 45.83'

**Bearing Trees, Reference Objects**  
OAK OAK Fence Corner  
10" 10" 5 1/2 W  
S57 1/4 E S46 1/2 W S87 1/2 W  
68 LKS 120 LKS 50 LKS

G-13 T. 144 R. 31

**Subsequent Corner Restoration**  
 Year surveyed 1979 By HWY DEPT  
 Location filed \_\_\_\_\_  
 Monument FD 2" CAPPED IRON PIPE, DOWN 0.3'  
RR SPK SE 35.4  
RR SPK SE 57.0

**Evidence of Subsequent Corner Restoration Found**  
 Year of search \_\_\_\_\_ By \_\_\_\_\_

Re monumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
 Filed at \_\_\_\_\_ Date \_\_\_\_\_