


Index No. G.0-25.0

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5th Coordinates: X _____ Y _____

E 1/4 12 Corner common to sections 12 and 7-144-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Jack Pine</u>	<u>Burr Oak</u>	_____
Diameter	<u>6"</u>	<u>3"</u>	_____
Bearing	<u>S 37° E</u>	<u>N 68° W</u>	_____
Distance	<u>20 links</u>	<u>45 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 4/1930 By H.D. Craig, U.S. Surveyor, GLO
Location filed: MN Hist. Soc., 144-30 notes pg 27 1/4
Monument: Set 1"x 3' iron pipe. w/brass cap S12 | S7
at proportionate distance, up 6" and mark
new witnessed as follows. 1930

Evidence of Subsequent Corner Restoration

Year of search 3/1992 By G. Brama, USFS
Location filed: USFS Field Book 1, page 45
Monument: Found Brass capped Iron pipe
30' S. of FS Rd. #3917 and lists witnesses as follows.

Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Norway Pine</u>	_____
Diameter	<u>7"</u>	<u>14"</u>	_____
Bearing	<u>N 39 3/4° E</u>	<u>S 49 1/2° W</u>	_____
Distance	<u>31 links</u>	<u>39 links</u>	_____

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Steel Sign</u>	_____
Diameter	<u>23"</u>	<u>Post</u>	_____
Bearing	<u>S 50° W</u>	<u>South</u>	_____
Distance	<u>25.7'</u>	<u>3'</u>	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

