


T. 144 R. 31 M. 514 Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 15 Corner common to sections 10, 11, 14, 15



EXISTING SURVEYS

Original Government Survey			
Year surveyed <u>1875</u>			
Original monument <u>Post</u>			
Bearing Trees			
Species	J. Pine	J. Pine	N. Pine
Diameter	<u>9"</u>	<u>12"</u>	<u>24"</u>
Bearing	<u>S 18 E</u>	<u>S 51 W</u>	<u>N 30 E</u>
Distance	<u>5 LKS</u>	<u>11 LKS</u>	<u>25 LKS</u>

Original Evidence Found	
Year of search _____	By _____
Monument found _____	
Original Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration	
Year surveyed <u>1914</u>	By <u>JOHN CURO</u>
Location filed <u>COUNTY SURVEY RECORD BOOK "B" P. 312-319</u>	
Monument <u>END OLD GAULT B.T.S: 9" J. PINE S 18 E 5 LKS.</u>	
<u>12" J. PINE S 51 W 11 LKS, 8" J. PINE N 65 W 25 LKS, STUMP</u>	
<u>24" N. PINE N 30 E 25 LKS</u>	
<u>1922, E. B. HORST, BOOK "D" P. 68, END CORNER.</u>	

Evidence of Subsequent Corner Restoration	
Year of search <u>1930</u>	By <u>GLO</u>
End stump of NE B.T. set concrete mon 24" long	
<u>6" DIA w/ brass cap</u>	<u>T 144 N R 31 W</u>
	<u>S 10 1/2 W</u>
	<u>S 15 1/2 W</u>
	<u>1930</u>

Bearing Trees, Reference Objects			
Species	J. PINE	J. PINE	J. PINE
Diameter	<u>14"</u>	<u>13"</u>	<u>12"</u>
Bearing	<u>S 55 W</u>	<u>S 50 E</u>	<u>N 58-30 E</u>
Distance	<u>84.57'</u>	<u>64.22'</u>	<u>60.33'</u>
	<u>1919 TIES</u>		<u>74.74'</u>

Bearing Trees, Reference Objects			
Species	J. Pine	J. Pine	N. Pine
Diameter	<u>5"</u>	<u>8"</u>	<u>15"</u>
Bearing	<u>N 32 3/4 E</u>	<u>S 53 1/2 E</u>	<u>S 50 3/4 W</u>
Distance	<u>62 LKS</u>	<u>35 LKS</u>	<u>200 LKS</u>
	<u>Fence cor. S 61 W 70 LKS fences w/ 5</u>		

J-17

Subsequent Corner Restoration	
Year surveyed <u>1917</u>	By <u>HORST</u>
Location filed <u>microfilm - roll 1105 BK 68 P. 39</u>	
Monument <u>End spike set by Curo from all</u>	
<u>GAULT B.T.S - also find Curo's 1914 B.T.S</u>	
<u>all cut down. Drove nails in stumps</u>	
<u>for B.T.S</u>	
<u>BK 68 P. 41 set 1 3/4 x 36" capped pipe</u>	

Evidence of Subsequent Corner Restoration Found		
Year of search <u>2000</u>	By <u>CCSO</u>	
End. GLO Monument down 0.8' in		
Rd. intersections <u>SEC. R. 144 &amp; 56th Ave.</u>		
REF. TIES:		
* 12" J. Pine (dead)	<u>N 33° W</u>	<u>67.01'</u>
P. Pole (fd. 8pnail)	<u>N 55° E</u>	<u>55.28'</u>
* distance to dbl. hd. nail		
<u>14" N. Pine</u>	<u>N 12° W</u>	<u>130.45'</u>
<u>8" N. Pine</u>	<u>S 63° W</u>	<u>122.75'</u>
<u>18" N. Pine</u>	<u>S 20° E</u>	<u>184.69'</u>

July 1923, Twp rd order shows no survey