


T. 144 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

E 1/4 23 Corner common to sections 23, 24



23

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1875  
Original monument Post

Original Evidence Found

Year of search 1903 by COE  
Monument found \_\_\_\_\_  
Leech Lake Reservoir

Bearing Trees

Species	<u>Norway Pine</u>	<u>Norway Pine</u>	_____
Diameter	<u>12"</u>	<u>12"</u>	_____
Bearing	<u>S 63° W</u>	<u>East</u>	_____
Distance	<u>116 links</u>	<u>130 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1903 By H. Dunaway, COE  
Location filed: Leech Lake Reservoir  
Monument:  
Indicates known corner

Evidence of Subsequent Corner Restoration

Year of search 9/1930 By H.D. Craig, U.S. Surveyor, GLO  
Location filed: MN Historical Society, notes page 29 1/4  
Monument: Set 1"x 3' iron pipe with brass cap S 23 | S 24  
from GLO witnesses stumps as follows. 1930

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>N. Pine stump</u>	<u>N. Pine stump</u>	<u>Jack Pine</u>	<u>Norway Pine</u>
Diameter	<u>20" GLO</u>	<u>16" GLO</u>	<u>10"</u>	<u>18"</u>
Bearing	<u>S 63°30' W</u>	<u>East</u>	<u>N 89°30' E</u>	<u>N 11°37' W</u>
Distance	<u>116 links</u>	<u>130 links</u>	<u>207 links</u>	<u>376 links</u>

Subsequent Corner Restoration

Year surveyed 2/1934 By J.A. Gjelhaug, Eng. CCC  
Location filed: USFS Form 874-9  
Monument: Found Brass capped 1" iron pipe  
lists witnesses as follows.  
14" Norway Pine, N 11 3/4° W, 27 links(17.82')  
18" J. Pine stump, S 62° W, 115 1/4 links(76.07')

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

8/1984, C. Krause, USFS  
T144N R31W Field Book 1, page 38  
Found iron pipe with brass cap, in good condition, 350'+/-, S.  
of road and witnesses as follows.  
Norway Pine stump, East, 85.8'(GLO) stump  
2.5"x 30" Aluminum monument, N 47° W, 23.86' flush  
2.5"x 30" Aluminum monument, N 47° E, 23.92' flush  
Steel sign posts behind aluminum monuments.

