


T. 144 R. 31 M. 5th Coordinates: X _____ Y _____

N 1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>Elm</u>	_____
Diameter	<u>16"</u>	<u>8"</u>	_____
Bearing	<u>S 78° W</u>	<u>N 63° E</u>	_____
Distance	<u>10 links</u>	<u>38 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 9/1930 By H.D. Craig, U.S. Surveyor, GLO
Location filed: MN Historical Society, notes page 19
Monument: Set 1"x 36" iron pipe w/brass cap
at proportionate distance, no remains of original
post or bearing trees, up 6" and witnessed.

1/4 S 25
S 36
1930

Evidence of Subsequent Corner Restoration

Year of search 6/1934 By Wilkenson Township
Location filed: Twp. Road Order, #5
Monument: Beginning at the Squaw Point Road in Sec. 36 in Township 144
Range 31, running South on the line between the lands owned
by John Dick Sr. NW 1/4-NE 1/4 and Indian Allotment NE 1/4 -
NW 1/4

Bearing Trees, Reference Objects

Species	<u>Burr Oak</u>	<u>Poplar</u>	_____
Diameter	<u>4"</u>	<u>9"</u>	_____
Bearing	<u>S 65°30' W</u>	<u>N 13°30' W</u>	_____
Distance	<u>64 links</u>	<u>10 links</u>	_____

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 2/1935 By J.A. Gjelhaug, Engineer, CCC
Location filed: USFS Form 874-9
Monument: Found brass capped 1" pipe
up 8" and placed metal location poster on witness as follows.
6" Aspen, N 14° W, 10 links

8/1963, W.H. Okerman, LS 6807
USFS Field Book 1, page 16
Searched for 2.5 hours, fund no evidence.

10/1975, C.R. Krause, USFS
USFS Field Book 1, page 16
GLO iron has been taken out by Road construction, we found
GLO Oak witness, dug down in road and found rust core, set
1"x 24" iron pipe in rust core, in centerline of N-S road and
witnesses as follows.
9" White Oak, S 65° W, 42.2'(1930) scribe visible
6" White Oak, S 31° E, 55.75' nail
7" Red Oak, N 85° E, 56.0' nail
4" Red Oak, West, 13.0' FSLP


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. N23

CASS COUNTY LAND CORNER RECORD

T. 144 R. 31 M. 5th Coordinates: X _____ Y _____
N1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species Aspen Elm _____
Diameter 16" 8" _____
Bearing S78W N63E _____
Distance 10 LKS 38 LKS _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1930 By GLD
Location filed Sec. of state
Monument Set 1x36" l.p. w/brass cap 11 525
14 536
1930

Evidence of Subsequent Corner Restoration

Year of search July 1934 By _____
Twp rd order shows no survey

Bearing Trees, Reference Objects

Species Br. oak Poplar _____
Diameter 4" 9" _____
Bearing S65-30W N13-30W _____
Distance 64 LKS 10 LKS _____

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____