


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. E 9

CASS COUNTY LAND CORNER RECORD

T. 145 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 8 Corner common to sections 4, 5, 8, 9



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Bearing Trees
Species N. Pine N. Pine
Diameter 14" 13"
Bearing N26E N1W
Distance 34.45 18.65

Original Evidence Found

Year of search _____ By _____
Monument found _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1926 By Co. Hur Dept.
Location filed RK# 156 - Box - "Field Notes"
Monument wood stake 488' N. of road

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Evidence of Subsequent Corner Restoration

Year of search 1958 By Pete Meyer
Set 2" x 5' galvanized wrought iron pipe filled with concrete and capped with 3" stamped bronze tablet.

Bearing Trees, Reference Objects

<u>B. Pine</u>	<u>Maple</u>	<u>W. Pine</u>	<u>R. Oak</u>
<u>16"</u>	<u>5"</u>	<u>17"</u>	<u>6"</u>
<u>N 33 W</u>	<u>S 60 W</u>	<u>N 76 E</u>	<u>N 61 E</u>
<u>52.3'</u>	<u>36.8'</u>	<u>71.0'</u>	<u>35.0'</u>

Subsequent Corner Restoration

Year surveyed ? By FREEMAN
Location filed _____
Monument 6' NORTH OF SWAMP, 18' NE OF STA. 284+77.9
9" R. OAK N 45 W 14.22
3" R. OAK S 25 W 5.09

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1958

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____