


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



EXISTING SURVEYS

Original Government Survey

Original Evidence Found

Year surveyed _____

Year of search _____ by _____

Original monument _____

Monument found _____

Bearing Trees

Original Bearing Trees Found

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____

Monument: _____

Monument: _____

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects

Species _____

Species _____

Diameter _____

Diameter _____

Bearing _____

Bearing _____

Distance _____

Distance _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found

Year surveyed _____ By _____

Year of search _____ By _____

Location filed: _____

Location filed: _____


Monument: _____

Monument: _____

Index No. N 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 574 Coordinates: X _____ Y _____
NE 24 Corner common to sections 13, 24 AND 18, 19-145-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument bst

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>J. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>	<u>J. Pine</u>
<u>12"</u>	<u>8"</u>	<u>10"</u>	<u>7"</u>
<u>N31E</u>	<u>N19W</u>	<u>S65W</u>	<u>S60E</u>
<u>23LKS</u>	<u>15LKS</u>	<u>46LKS</u>	<u>12LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1963 By Okerman - USFS
Location filed _____
Monument Found stump holes and/or charred pine
stumps for all 4 GLO B.T.S
Set 2x60" 1/2" w/ 3" bronze cap
sign post South 4.25'

Evidence of Subsequent Corner Restoration

Year of search 1979 By DNR - Engineering
maps notes in file
Found Okermans monument w/ 1.7'

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>J. Pine</u>	<u>oak</u>	<u>oak</u>	<u>J. Pine</u>
<u>15"</u>	<u>6"</u>	<u>6"</u>	<u>11"</u>
<u>N65 1/2 W</u>	<u>N44E</u>	<u>S16 1/2 E</u>	<u>S53 1/2 W</u>
<u>61.3'</u>	<u>126.5'</u>	<u>137.5'</u>	<u>56.7'</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1986 By Walt Curo
Location filed Corner Certificate - Doc # 291630
Monument Find 2x60" 1/2" w/ brass cap as set
in 1963, Certificate is to update old
certificate
5" N. Pine N40°W 19.92'
7" N. Pine N5°E 17.60'
8" N. Pine N80°E 10.06'
5" N. Pine S23°E 42.01'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1963
Certificate - Walt Curo - 1986 - update

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____