


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Page _____ of _____

Corner common to sections _____

Subsequent Corner Restoration

Evidence of Subsequent Corner Restoration Found


Year surveyed _____ By _____
Location filed:
Monument:

Year of search _____ By _____
Location filed:
Monument:

Index No. R 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5TH Coordinates: X _____ Y _____
NE 25 Corner common to sections 24, 25 AND 19, 30 - 145-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873

Original monument Post

Species	Bearing	Trees	Distance
<u>N. Pine</u>	<u>N 174° W</u>	<u>160 LKS</u>	
<u>N. Pine</u>	<u>N 52° E</u>	<u>160 LKS</u>	
<u>N. Pine</u>	<u>S 88° W</u>	<u>25 LKS</u>	
<u>N. Pine</u>	<u>S 75° E</u>	<u>58 LKS</u>	

Original Evidence Found

Year of search _____ By _____

Monument found _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 1974 By BLM

Location filed sec. of state

Monument End 5" concrete man w/ brass cap 2" under S. edge of Hwy 2 set by T145N RLS # 6807

Bearing Trees, Reference Objects 524 519 525 530 1968 RLS # 6807

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1979 By DNR-Engineering

Map & notes in file

Found 3" brass cap monument 0.15' below surface of Hwy 17.1' S. of & Hwy 2

Bearing Trees, Reference Objects

J. Pine	R. oak	R. oak	Red. Pine
<u>10"</u>	<u>8"</u>	<u>9"</u>	<u>21"</u>
<u>N 55° E</u>	<u>S 40° E</u>	<u>S 36° W</u>	<u>N 46° W</u>
<u>155.95'</u>	<u>134.84'</u>	<u>101.90'</u>	

1968 USFS TIES

R-25 Subsequent Corner Restoration

Year surveyed 1986 By Walt Curo

Location filed Corner Certificate - Doc # 291635

Monument End brass cap set in concrete as per previous surveys.

Corner is 171' S. of & US. Hwy 2, down 2"

24" N. Pine N 46° W 197.95' (1968 tie)

5" Burr oak N 15° E 113.55'

10' Red oak S 40° E 134.84' (1968 tie)

5" N. Pine S 70° W 140.32'

MARCH 1999, T. LARSON - MN/DOT - FOUND MON. & WITNESSES

CASS Co NORTH HAEN N = 91657.449 m

E = 146944.148 m

11/03 - Landecker & Assoc Cert of Survey indicates found monument.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____

PLAT - PORTAGE LAKE

R.L. WARNER 1925

Certificate - Walt Curo - 1986