


Index No. X 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
E 1/4 36 Corner common to sections 36 AND 31-145-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees	
Species <u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>12"</u>	<u>14"</u>
Bearing <u>N70W</u>	<u>N81E</u>
Distance <u>31 LKS</u>	<u>49 LKS</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1974 By BLM  
Location filed Sec. of state  
Monument Find 5" concrete men w/ brass cap set  
N 26-48E 540 LKS from proportional position T145N

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects			
Species <u>R. Pine</u>	<u>R. Pine</u>	<u>R. Oak</u>	<u>530/531</u>
Diameter <u>13"</u>	<u>10"</u>	<u>10"</u>	<u>114</u>
Bearing <u>N40E</u>	<u>N19W</u>	<u>S37W</u>	<u>1968</u>
Distance <u>149 LKS</u>	<u>172 LKS</u>	<u>77 LKS</u>	<u>RLS# 6007</u>

Bearing Trees, Reference Objects

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_