


Index No. \_\_\_\_\_

CASS COUNTY LAND CORNER RECORD

T. \_\_\_\_\_ R. \_\_\_\_\_ M. \_\_\_\_\_ Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

Corner common to sections \_\_\_\_\_



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed \_\_\_\_\_  
Original monument \_\_\_\_\_

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Bearing Trees, Reference Objects

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed:  
Monument:

Index No. 221

CASS COUNTY LAND CORNER RECORD

T. 145 R. 29 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
SE 35 Corner common to sections 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Bearing Trees	
Species <u>Bl. Pine</u>	<u>Bl. Pine</u>
Diameter <u>12"</u>	<u>8"</u>
Bearing <u>N75E</u>	<u>N68W</u>
Distance <u>26 LKS</u>	<u>11 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Bearing Trees Found	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Subsequent Corner Restoration

Year surveyed 1926 By GLO  
Location filed Sec. of State  
Monument End decayed wood stake i both B.T.S dead.  
Set 2 x 36" W. W. brass cap  
S.C.  
T145N/R29W  
S35/S36

Bearing Trees, Reference Objects 1926

Bearing Trees, Reference Objects	
Species <u>N. Pine</u>	<u>N. Pine</u>
Diameter <u>14"</u>	<u>12"</u>
Bearing <u>N42-45W</u>	<u>N73-30W</u>
Distance <u>86 LKS</u>	<u>33 LKS</u>

Evidence of Subsequent Corner Restoration

Year of search 1974 By BLM  
End 2" W. W. brass cap  
and stump holes of both  
orig B.T.S.  
S.C.  
T145N R29W  
S35/S36  
1926

Bearing Trees, Reference Objects

Bearing Trees, Reference Objects		
<u>Red Pine</u>	<u>Red Pine</u>	<u>Red Pine</u>
<u>22"</u>	<u>19"</u>	<u>20"</u>
<u>N73 1/2 E</u>	<u>N42 3/4 W</u>	<u>N25W</u>
<u>33 LKS</u>	<u>86 LKS</u>	<u>91 LKS</u>
<u>1926 B.T.S.</u>		<u>1967 B.T.</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKEMAN - 1967  
Found GLO monument in good condition  
19" N. PINE N25W 60.80"

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_