


T. 145 R. 29 M. 5th Coordinates: X _____ Y _____
SE 36 Corner common to sections 31-145-28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Bearing Trees

Species	<u>Y. Pine</u>	<u>B. Pine</u>		
Diameter	<u>19"</u>	<u>9"</u>		
Bearing	<u>N40°E</u>	<u>N66°W</u>		
Distance	<u>411ks</u>	<u>911ks</u>		

Original Evidence Found

Year of search 1924 By USFS
Monument found Square N. Pine

Original Bearing Trees Found

Species	<u>South side of 300 line R/W</u>
Diameter	<u>Just west of platform on</u>
Bearing	<u>North side. Original was</u>
Distance	<u>in cut.</u>

Subsequent Corner Restoration

Year surveyed 7-5-67 By J. Ekstrom
Location filed USFS T145N R28W BK 1
Monument No evidence found at 1924 location

Evidence of Subsequent Corner Restoration

Year of search 7-8-68 By W. Okerman
Set concrete cylinder with brass cap at proportional measurement from cadastral survey. 110° E S. of R/R Tracks.

Bearing Trees, Reference Objects

Species				
Diameter				
Bearing				
Distance				

Bearing Trees, Reference Objects

<u>R. Pine</u>	<u>R. Pine</u>	<u>R. Pine</u>	<u>J. Pine</u>
<u>3"</u>	<u>5"</u>	<u>7"</u>	<u>8"</u>
<u>N39°E</u>	<u>N6°E</u>	<u>N18°W</u>	<u>N58°W</u>
<u>37.0'</u>	<u>42.37'</u>	<u>41.34'</u>	<u>23.36'</u>

225

Subsequent Corner Restoration

Year surveyed 8-14-87 By C. Krause
Location filed USFS T145N R28W BK 1
Monument 1968 conc. cyl. in good condition. R. Pine witnesses good and following:

N. Pine 17" N54°W, 54.50
J. Pine 17" N17°E, 80' FSLP
Steel Post West 4.0'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____