


Index No. E 13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
NE 9 Corner common to sections 3, 4, 9, 10



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Bearing Trees

Species	<u>Y. Pine</u>	<u>Y. Pine</u>	<u>Sl. Pine</u>
Diameter	<u>12"</u>	<u>12"</u>	<u>8"</u>
Bearing	<u>S1E</u>	<u>S46W</u>	<u>N23W</u>
Distance	<u>93 LKS</u>	<u>100 LKS</u>	<u>156 LKS</u>

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1933 By GLO  
Location filed Sec. of State  
Monument Set concrete man 24" long 6" dia w/ brass cap in center of road on E-W blazd line  
Engineer who surveyed Blackduck road 7145N R 30W  
Said cor. was in center of road 54153

Bearing Trees, Reference Objects

Species	<u>N. Pine</u>	<u>Stone</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>J. Pine</u>
Diameter	<u>12"</u>	<u>3"</u>	<u>3"</u>	<u>3"</u>	<u>8"</u>
Bearing	<u>N33E</u>	<u>S43E</u>	<u>S54W</u>	<u>N51W</u>	
Distance	<u>104 LKS</u>	<u>89 LKS</u>	<u>97 LKS</u>	<u>153 LKS</u>	

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_