


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 14 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species Black Pine Black Pine
Diameter 6" 6"
Bearing N 32° E S 87° W
Distance 41 links 20 links

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 6/1933 By W.W. Bandy, Surveyor
Location filed: Resurvey Notes 1/4 S 11
Monument: Set 1" OD iron pipe with brass cap S 14
At proportionate position, no original evidence. 1933

Evidence of Subsequent Corner Restoration

Year of search 3/1962 By R.H. McDonald, USFS
Location filed: USFS Book 1, page 77
Monument: Found GLO iron pipe with brass cap

Bearing Trees, Reference Objects

Species Norway Pine Norway Pine
Diameter 14" 20"
Bearing N 11° E S 79° E
Distance 74 links 93 links

Bearing Trees, Reference Objects

Species Norway Pine Norway Pine Jack Pine
Diameter 19"(1933) 23"(1933) 9"
Bearing N 11° E S 79° E S 80° E
Distance 48.84' 61.38' 9.65'

Subsequent Corner Restoration

Year surveyed 11/1996 By C.R. Krause, USFS
Location filed: USFS Book 1, page 77
Monument: Found GLO iron pipe with brass cap
up 7", 100'+/- W. of Tank Trapped Roads. Found the 1933 and
1962 witnesses and added.
Steel Sign Post, South, 2.55'

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____


4/2010, Kadrmas, Lee & Jackson
Certificate of Location
Found GLO iron pipe with brass cap, up 0.8' in good condition.
24" Norway Pine, N 11° E, 48.84' (1933)
8" Jack Pine, N 89° E, 28.21' spike in N. side
6" Red Pine, S 15° W, 18.91' spike in E. side
10" Red Pine, S 87° W, 16.24' spike in N. side
Steel Sign Post, South, 2.55' (1996)

4/2014, R. Wamre, LS 45334
Certificate of Location, Doc. #A000601386
Filed on the above information.

Index No. J19

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 574 Coordinates: X _____ Y _____
N 1/4 14 Corner common to sections 11, 14



EXISTING SURVEYS

Original Government Survey

Year surveyed 1879
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees
Species B. Pine B. Pine
Diameter 6" 6"
Bearing N32E S87W
Distance 41 LKS 20 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1933 By GLO
Location filed Sec. of State
Monument Set 1x36" 1/4" brass cap 1/4 511
514
1933

Evidence of Subsequent Corner Restoration

Year of search 1962 By PETE MEYER
Found GLO monument in good condition

Bearing Trees, Reference Objects
Species N. Pine N. Pine
Diameter 14" 20"
Bearing N11E S79E
Distance 74 LKS 93 LKS

Bearing Trees, Reference Objects
N. Pine J. Pine
19" 9"
N11E S80E
48.84' 9.65'

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____