


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
E 1/4 16 Corner common to sections 15, 16



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search 1933 by Bandy
Monument found _____
Notes page 64

Bearing Trees

Species White Oak Black Oak
Diameter 8" 16"
Bearing S 27° E S 6° W
Distance 34 links 64 links

Original Bearing Trees Found

Species White Oak
Diameter 14"
Bearing S 27° E
Distance 34 links

Subsequent Corner Restoration

Year surveyed 12/1929 By A.W. Prudlo, Asst. Engr.
Location filed: Ditch Shelf 1, Book 167, page 2
Monument: No mon
S.R. #10 Transit notes, indicates 1/4 line PI at station 12+35.0 and reference points as follows.

Evidence of Subsequent Corner Restoration

Year of search 7/1933 By W.W. Bandy, Surveyor, GLO
Location filed: MN Historical Society, Notes page 63 1/4
Monument: Set 1"x 3' iron post with brass cap S 16 | S 15 from remains of original witness, up 9", 105 links(69.3') W. of centerline of Black 1933 Duck road and marked new witnesses as follows.

Bearing Trees, Reference Objects

Species Poplar Pop
Diameter 5" 8"
Bearing SE SW
Distance 60.1' 57.4'

Bearing Trees, Reference Objects

Species Black Oak Black Oak
Diameter 8" 7"
Bearing S 22 1/2° E N 17 1/2° W
Distance 57 links 55 links

Subsequent Corner Restoration

Year surveyed 3/1934 By J.A. Gjelhaug, Engineer, CCC
Location filed: USFS Form 874-9
Monument: Found brass capped 1 1/2" iron pipe up 10" and witnesses as follows.
6" White Oak, N 20° W, 54 1/2 links(35.97')
5" White Oak, S 24° E, 56 links(36.96')

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____


5/1966, M. Hansey, USFS
USFS Book 2, page 14
Found GLO iron with brass cap and witnesses as follow.
10" Oak, S 22° E, 37.3'(1933) rescribed
10" Oak, N 17° W, 36.3'(1933) rescribed

2/2001, CCHD/SO
#2001.002
Found GLO brass cap monument, up 1.0', 65' W. of centerline Co. Rd. #10 and witnessed.
13" White Oak, N 17° W, 36.28'(1933) duplex nail
12" White Oak, S 22° E, 37.14'(1933) duplex nail
5" Burr Oak, S 83° W, 45.23' duplex nail

Index No. L 13

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
E 1/4 16 Corner common to sections 15, 16



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1879
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species W. oak Bl oak
Diameter 8" 16"
Bearing S 27 E S 6 W
Distance 34 LKS 64 LKS

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed 1933 By GLO
Location filed Sec of State
Monument Find SE BIT - NOW 14" Set 1x36" 1/4".
Witness cap
Cor. approx 105 LKS W of C of F 516/515
Blackduck road 1933

Evidence of Subsequent Corner Restoration

Year of search 1966 By William OKerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species Bl oak Bl oak
Diameter 8" 7"
Bearing S 22 1/4 E N 17 1/2 W
Distance 57 LKS 55 LKS

Bearing Trees, Reference Objects

Oak Oak
10" 10"
S 22 E N 17 W
37.3' 36.3'

L 13

Subsequent Corner Restoration

Year surveyed 2/2001 By CCSO
Location filed CCSO
Monument Found GLO Brass cap monument
up 1.0', 65'± W. of C. #10. Add
Nails to 1966 witnesses.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

13" W. Oak N 17° W, 36.28* (1966)

12" W. Oak S 22° E, 37.14* (1966)

5" W. Oak S 83° W, 45.23*

*distance to double head nail

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____