


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

C 1/4 Corner common to sections 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 7/1933 C 1/4 S 23

Original monument 2"x 36" I.P. w/brass cap 1933

Dependent resurvey, W.W. Bandy, Surveyor

Original Evidence Found

Year of search _____ by _____

Monument found _____

Bearing Trees

Species Poplar Poplar _____

Diameter 5" 5" _____

Bearing S 1 1/2° E S 70 1/2° W _____

Distance 66 links 107 links _____

Original Bearing Trees Found

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed 5/1966 By J. Ekstrom, USFS

Location filed: USFS Book 1, page 72

Monument: Found GLO brass cap and decayed stump of SE witness tree.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Location filed: _____

Monument: _____

Bearing Trees, Reference Objects

Species Elm Ash Steel Sign _____

Diameter 6" 5" Post _____

Bearing N 14° W N 56° W West _____

Distance 38.5' 10.8' 5.5' _____

Bearing Trees, Reference Objects

Species _____

Diameter _____

Bearing _____

Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____

Location filed: _____

Monument: _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____


Location filed: _____

Monument: _____

Index No. P19

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
C/4 Corner common to sections 23



EXISTING SURVEYS

Original Government Survey

Year surveyed 1933 C/4 533
Original monument 1x36" l.p. w/ brass cap 1933

Original Evidence Found

Year of search _____ By _____
Monument found _____

	Bearing Trees	
Species	<u>Poplar</u>	<u>Poplar</u>
Diameter	<u>5"</u>	<u>5"</u>
Bearing	<u>S1 1/2 E</u>	<u>S70 1/4 W</u>
Distance	<u>66 LKS</u>	<u>107 LKS</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 1966 By William Okerman
Location filed _____
Monument Found GLO monument in good condition.

Evidence of Subsequent Corner Restoration

Year of search _____ By _____

Bearing Trees, Reference Objects

Species	<u>Elm</u>	<u>Ash</u>
Diameter	<u>1 1/2"</u>	<u>5"</u>
Bearing	<u>N14 W</u>	<u>N56 W</u>
Distance	<u>38.5'</u>	<u>10.8'</u>

Bearing Trees, Reference Objects

_____	_____
_____	_____
_____	_____
_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____