

T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

N 1/4 28 Corner common to sections 21, 28



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>Aspen</u>	_____
Diameter	<u>4"</u>	<u>4"</u>	_____
Bearing	<u>N 31° W</u>	<u>S 17° E</u>	_____
Distance	<u>30 links</u>	<u>60 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1933 By W.W. Bandy, Surveyor
Location filed: MN Historical Society, Notes page 70
Monument: Set 6" concrete cylinder with brass cap S 21
at proportionate distance, no evidence of 1/4 _____
original bearing trees or post and witnessed S 28
as follows. 1933

Evidence of Subsequent Corner Restoration

Year of search 5/1966 By J. Ekstrom, USFS
Location filed: USFS Book 2, page 5
Monument: Found GLO concrete with brass cap
busted off, reset monument, placed FSLP on 4" Cedar Post,
West, 34.2' on E. side of Cuba Hill road and witnessed as
follows.

Bearing Trees, Reference Objects

Species	<u>Red Oak</u>	<u>White Birch</u>	_____	_____
Diameter	<u>10"</u>	<u>6"</u>	_____	_____
Bearing	<u>N 62° E</u>	<u>S 38 1/2° W</u>	_____	_____
Distance	<u>22 links</u>	<u>59 links</u>	_____	_____

Bearing Trees, Reference Objects

Species	<u>White Birch</u>	<u>Maple</u>	<u>Oak</u>	<u>Cedar Post</u>
Diameter	<u>6" (1933)</u>	<u>5"</u>	<u>6"</u>	<u>4"</u>
Bearing	<u>S 38° W</u>	<u>S 37° W</u>	<u>N 43° W</u>	<u>North</u>
Distance	<u>38.94'</u>	<u>6.3'</u>	<u>25.6'</u>	<u>2.0'</u>

Subsequent Corner Restoration

Year surveyed 9/1978 By M.E. Stefan, LS 12261
Location filed: USFS Book 2, page 5
Monument: Found corner
lists witnesses as follows.
Oak, N 43° W, 25.6' (1966) overgrown and live
8" White Oak, N 25° E, 49.66'
10" Red Oak, S 67° W, 107.26'


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. R11

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
N114 28 Corner common to sections 21, 28



○ = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1874
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Aspen Aspen
Diameter 4" 4"
Bearing N31W S17E
Distance 30 LKS 60 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1933 By GLO
Location filed Sec. of State
Monument Set Concrete mon 24" long 6" Dia w/ brass cap
1/4 521
528
1933

Evidence of Subsequent Corner Restoration
Year of search 1966 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects
Species R. oak w. Birch
Diameter 10" 6"
Bearing N62E S38 1/2 W
Distance 22 LKS 59 LKS

Bearing Trees, Reference Objects
Maple Oak
5" 6"
S37W N43W
6.3' 25.6'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1966

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____