


T. 145 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

N 1/4 26 Corner common to sections 23, 26



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Aspen</u>	<u>Blk. Pine</u>	_____
Diameter	<u>6"</u>	<u>8"</u>	_____
Bearing	<u>N 20° W</u>	<u>S 62° W</u>	_____
Distance	<u>44 links</u>	<u>17 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 6/1933 By W.W. Bandy, Surveyor  
Location filed: Resurvey Notes  
Monument: Set 1"x 36" iron post with brass cap at proportionate distance. S 23  
1/4 S 26  
1933

Evidence of Subsequent Corner Restoration

Year of search 1/1962 By R.H. McDonald, USFS  
Location filed: USFS Book 1, page 63  
Monument: Found GLO brass cap and witnesses.  
Steel Sign Post, East, 2.36'

Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Elm</u>	_____
Diameter	<u>12"</u>	<u>6"</u>	_____
Bearing	<u>N 16 1/2° W</u>	<u>S 33° E</u>	_____
Distance	<u>30 links</u>	<u>48 links</u>	_____

Bearing Trees, Reference Objects

Species	<u>Jack Pine</u>	<u>Elm</u>	<u>Elm</u>	<u>Elm</u>
Diameter	<u>14" (1933)</u>	<u>10" (1933)</u>	<u>8"</u>	<u>13"</u>
Bearing	<u>N 16 1/2° W</u>	<u>down</u>	<u>S 1° W</u>	<u>N 64 1/2° W</u>
Distance	<u>19.8'</u>	<u>32'</u>	<u>30.3'</u>	<u>34.6'</u>

Subsequent Corner Restoration

Year surveyed 1/1986 By C.R. Krause, USFS  
Location filed: USFS Book 1, page 63  
Monument: Found GLO brass cap lists witnesses.  
J. Pine stump, N 16° W, 19.8' (1933)  
11" Elm, S 1° W, 30.3' (1962)  
16" Elm, N 65° W, 34.6' (1962)  
17" W. Oak, S 40° E, 46.2' 50d spike  
9" W. Oak, N 50° E, 31.05' 50d spike  
15" W. Ash, S 81° W, 19.3' 50d spike  
6" W. Spruce, S 60° E, 4.5' FSLP


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

Index No. R19

CASS COUNTY LAND CORNER RECORD

T. 14S R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
N 14 26 Corner common to sections 23, 26



EXISTING SURVEYS

Original Government Survey  
Year surveyed 1879  
Original monument Post

Original Evidence Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Aspen Bl. Pine  
Diameter 6" 8"  
Bearing N20W S62W  
Distance 44LKS 17LKS

Original Bearing Trees Found  
Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration  
Year surveyed 1933 By GLO  
Location filed Sec. of State  
Monument Set 1x36" 11P. w/ brass cap 1/4 523  
526  
1933

Evidence of Subsequent Corner Restoration  
Year of search 1962 By PETE MEYER  
Found GLO monument in good condition

Bearing Trees, Reference Objects  
Species J. Pine Elm  
Diameter 12" 6"  
Bearing N16 1/2 W S33E  
Distance 30 LKS 48 LKS

Bearing Trees, Reference Objects  
Elm Elm  
8" 13"  
S11W N64 1/2 W  
30.3' 34.6'

Subsequent Corner Restoration  
Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found  
Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_