


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 36 Corner common to sections 25, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search 1933 by Bandy
Monument found Cedar Post

Resurvey Notes

Bearing Trees

Species Tamarack Tamarack
Diameter 10" 6"
Bearing S 45° E N 53° W
Distance 32 links 11 links

Original Bearing Trees Found

Species Tamarack Tamarack
Diameter Stump Decayed Stp
Bearing S 45° E N 52° W
Distance 27 links 11 links

Subsequent Corner Restoration

Year surveyed 1900-03 By T.M. Fowble, COE
Location filed: Leech Lake and Winnibigoshish Reservoir Map
Monument:
Map indicates a known corner.

Evidence of Subsequent Corner Restoration

Year of search 6/1933 By W.W. Bandy, Surveyor
Location filed: Resurvey Notes, MN Historical Soc.
Monument: Set 1" OD iron pipe with brass cap
from original evidence and witnessed.

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species Cedar Cedar
Diameter 6" 8"
Bearing N 10° E S 82° W
Distance 26 links 34 links

Subsequent Corner Restoration

Year surveyed 1/1962 By R.H. McDonald, USFS
Location filed: USFS Book 1, page 24
Monument: Found GLO iron pipe with brass cap
Found square scribed cedar post laying beside corner and
witnesses as follows.
Tamarack stump, S 45° E, 17.8' (1874) badly decayed
11" Cedar, N 10° E, 17.5' (1933) scribed
10" Cedar, S 82° W, 22.44' (1933) scribed
11" Cedar, S 26° E, 40.0'
Steel Sign Post, South, 1.75' 54-2 and 54-4

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

