


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

NE 36 Corner common to sections 25, 36 and 30, 31-145-29



● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	Poplar	Poplar	Poplar	Poplar
Diameter	5"	3"	4"	3"
Bearing	N 15° E	N 26° W	S 60° W	S 62° E
Distance	18 links	13 links	5 links	10 links

Original Bearing Trees Found

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1900-03 By T.M. Fowble, COE
Location filed: Leech Lake and Winnibigoshish Reservoir Map
Monument:
Map indicates a known corner.

Evidence of Subsequent Corner Restoration

Year of search 6/1933 By W.W. Bandy, Surveyor
Location filed: Resurvey Notes, MN Historical Soc. T145N
Monument: Set 6" concret cylinder w/brass tablet R30W R29W at proportionate distance. No remaining S 25 | S 30 evidence of original post or bearing trees. S 36 | S 31 1933

Bearing Trees, Reference Objects

Species	_____	_____	_____	_____
Diameter	_____	_____	_____	_____
Bearing	_____	_____	_____	_____
Distance	_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Yellow Birch	White Birch	Elm	Elm
Diameter	6"	6"	10"	10"
Bearing	N 60 3/4° E	S 80° E	S 29 1/4° W	N 25° W
Distance	33 links	23 links	56 links	15 links

Subsequent Corner Restoration

Year surveyed 4/1937 By H. Hennes, CCC
Location filed: USFS, Form 874
Monument: Brass cap in concrete 2" above ground and witnesses as follows. 10" Elm, N 27° W, 15 links (1933) 4" Y. Birch, N 60° E, 33 links (1933) 4.5" W. Birch, S 80° E, 23 links (1933) 12" Elm, S 29 1/4° W, 56 links (1933)

Evidence of Subsequent Corner Restoration Found


Year of search _____ By _____
Location filed: _____
Monument: _____

1/1962, R.H. McDonald, USFS
USFS Book 1, page 5
Found GLO concrete with brass tablet and witnessed.
12" Elm, S 30° W, 36.96' (1933)
Elm stump, N 25° W, 9.9' (1933) decayed
15" Cedar, N 81° W, 60.9'
5" Maple, N 30° E, 6.3'
9" Maple, S 65° E, 45.5'

Index No. V 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
NE 36 Corner common to sections 25, 36 and 30, 31 - 145-29



EXISTING SURVEYS

Original Government Survey
Year surveyed 1873
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Species	Bearing	Tree	Tree
<u>Poplar</u>	<u>5"</u>	<u>Poplar</u>	<u>Poplar</u>
<u>5"</u>	<u>3"</u>	<u>4"</u>	<u>3"</u>
<u>N15E</u>	<u>N26W</u>	<u>S60W</u>	<u>S62E</u>
<u>18 LKS</u>	<u>13 LKS</u>	<u>5 LKS</u>	<u>10 LKS</u>

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1933 By GLO
Location filed Sec. of State
Monument Set concrete mon 24" long 6" dia w/ brass cap
T145N
R30W R29W
S25 S30
S36 S31

Evidence of Subsequent Corner Restoration
Year of search 1962 By PETE MEYER
Found GLO monument in good condition.

Species	Bearing	Tree	Reference Objects
<u>Y. Birch</u>	<u>6"</u>	<u>W. Birch</u>	<u>Elm</u>
<u>6"</u>	<u>6"</u>	<u>10"</u>	<u>10"</u>
<u>N60 3/4 E</u>	<u>S80 E</u>	<u>S29 1/4 W</u>	<u>N25 W</u>
<u>33 LKS</u>	<u>23 LKS</u>	<u>56 LKS</u>	<u>15 LKS</u>

Species	Bearing	Tree	Reference Objects
<u>Cedar</u>	<u>15"</u>	<u>Maple</u>	<u>Maple</u>
<u>15"</u>	<u>5"</u>	<u>9"</u>	<u>9"</u>
<u>N81 W</u>	<u>N30 E</u>	<u>S65 E</u>	<u>S65 E</u>
<u>60.9'</u>	<u>6.3'</u>	<u>45.5'</u>	<u>45.5'</u>

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - PETE MEYER - 1962

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____