


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____
N 1/4 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Aspen</u>	<u>Aspen</u>
Diameter	<u>6"</u>	<u>4"</u>
Bearing	<u>N 20° W</u>	<u>N 42° E</u>
Distance	<u>14 links</u>	<u>20 links</u>

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 7/1933 By W.W. Bandy, Surveyor, GLO
Location filed: MN Historical Society, Notes page 44
Monument: Set 1"x 3' iron pipe with brass cap S 26
at proportionate distance, no remaining evidence 1/4 _____
of original post or bearing trees, up 9" and S 35
witnessed as follows. 1933

Evidence of Subsequent Corner Restoration

Year of search 4/1964 By J. Ekstrom, USFS
Location filed: USFS Book 2, page 20
Monument: Found GLO iron pipe
and witnessed as follow.

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>Poplar</u>
Diameter	<u>8"</u>	<u>12"</u>
Bearing	<u>N 24° E</u>	<u>S 64° W</u>
Distance	<u>65 links</u>	<u>17 links</u>

Bearing Trees, Reference Objects

Species	<u>Aspen(1933)</u>	<u>W. Pine(1933)</u>	<u>White Pine</u>	<u>Ash</u>
Diameter	<u>Stump</u>	<u>fallen</u>	<u>12"</u>	<u>7"</u>
Bearing	<u>S 64° W</u>	<u>N 24° E</u>	<u>N 77° W</u>	<u>N 19° E</u>
Distance	<u>11.22'</u>	<u>42.90'</u>	<u>40.0'</u>	<u>47.15'</u>

Subsequent Corner Restoration

Year surveyed 9/1976 By C.R. Krause, USFS
Location filed: USFS Book 2, page 20
Monument: Found GLO iron with brass cap
up 14", in good condition, 65'+/-, S. of wood trail, piled rocks
around iron pipe and witnessed as follows.
16" White Pine, N 77° W, 40.0'(1964) scribe visible
10" Ash, N 19° E, 47.15'(1964) scribe overgrown
6" Elm, S 24° W, 23.55' marked
9" Ash, N 57° E, 60.5' marked
Steel Sign Post, South, 2.2' FS 54-4 sign


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. V19

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
N114 35 Corner common to sections 26, 35



EXISTING SURVEYS

Original Government Survey
Year surveyed 1877
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species Aspen Aspen
Diameter 6" 4"
Bearing N20W N42E
Distance 14 LKS 20 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1933 By GLO
Location filed Sec. of State
Monument set 1x36" l.p. w/ brass cap 1/4 526
535
1933

Evidence of Subsequent Corner Restoration
Year of search 1964 By William Okerman
Found GLO monument in good condition

Bearing Trees, Reference Objects
Species W. Pine Poplar
Diameter 8" 12"
Bearing N24E S64W
Distance 65 LKS 17 LKS

Bearing Trees, Reference Objects
W. Pine Ash
12" 7"
N77W N19E
40.0' 47.15'

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1964