


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

E 1/4 34 Corner common to sections 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search 1933 by Bandy
Monument found _____

Resurvey Notes page 43

Bearing Trees

Species	<u>White Pine</u>	<u>White Pine</u>
Diameter	<u>24"</u>	<u>30"</u>
Bearing	<u>N 22° W</u>	<u>S 20° E</u>
Distance	<u>27 links</u>	<u>17 links</u>

Original Bearing Trees Found

Species	<u>N. Pine fallen</u>	<u>White Pine</u>
Diameter	<u>30"</u>	<u>30"</u>
Bearing	<u>S 20° E</u>	<u>N 58° W</u>
Distance	<u>17 links</u>	<u>27 links</u>

Subsequent Corner Restoration

Year surveyed 7/1933 By W.W. Bandy, Surveyor, GLO
Location filed: MN Historical Society, Notes pg 43 1/4
Monument: Set 1"x 3' iron pipe with brass cap S 34 | S 35
from remains of original bearing trees, up 16" 1933
and witnessed as follows.

Evidence of Subsequent Corner Restoration

Year of search 9/1976 By C.R. Krause, USFS
Location filed: USFS Book 2, page 37
Monument: Found GLO brass cap monument
up 14", in good condition, with rocks piled around iron, 725' W.
of woods trail and witnesses as follows.
30" White Pine, N 58° W, 17.8'(GLO) old blaze

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>White Pine</u>
Diameter	<u>30"</u>	<u>18"</u>
Bearing	<u>N 62 1/2° E</u>	<u>N 1 1/2° W</u>
Distance	<u>99 links</u>	<u>80 links</u>

Bearing Trees, Reference Objects

Species	<u>White Pine</u>	<u>White Oak</u>	<u>White Oak</u>	<u>Steel Sign</u>
Diameter	<u>24"(1933)</u>	<u>6"</u>	<u>6"</u>	<u>Post</u>
Bearing	<u>N 2° W</u>	<u>N 21° E</u>	<u>N 75° E</u>	<u>West</u>
Distance	<u>52.8'</u>	<u>36.95'</u>	<u>55.10'</u>	<u>1.9'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed: _____
Monument: _____


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. X 17

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
E14 34 Corner common to sections 34, 35



EXISTING SURVEYS

Original Government Survey
Year surveyed 1874
Original monument Post

Original Evidence Found
Year of search _____ By _____
Monument found _____

Bearing Trees
Species W Pine W Pine
Diameter 24" 30"
Bearing N22W S20E
Distance 27 LKS 17 LKS

Original Bearing Trees Found
Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration
Year surveyed 1933 By GLO
Location filed Sec. of state
Monument End SE B.T. (down) & NW B.T. New 30"
N58W set 1x36" 1/4" w/ brass cap 1/4
534/535
1933

Evidence of Subsequent Corner Restoration
Year of search _____ By _____

Bearing Trees, Reference Objects
Species W Pine W Pine
Diameter 30" 18"
Bearing N62 1/2 E N1 1/2 W
Distance 99 LKS 80 LKS

Bearing Trees, Reference Objects

Subsequent Corner Restoration
Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____
CERTIFICATE - MILO STEFAN - 1976
Doc. # 246230
found GLO monument in good condition
6" W. Oak N21E 36.95';
6" W. Oak N75E 55.10'