


T. 145 R. 30 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

S 1/4 33 Corner common to sections 33 and 4-144-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ by \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees

Species	<u>Sugar</u>	<u>Spruce</u>
Diameter	<u>8"</u>	<u>8"</u>
Bearing	<u>N 18° W</u>	<u>N 35° E</u>
Distance	<u>19 links</u>	<u>25 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, U.S. Surveyor, GLO  
 Location filed: MN Historical Society, Notes page 12  
 Monument: Set 2"x 3' iron pipe with brass cap SC  
 at record distance, evidence of original position 1/4 S 33  
 appears to have been destroyed, new witnesses 1930  
 as follows.  
 N 1/4 cor sec 4-144-30 is N 89°31' E, 38.63 Chains(2549.58')  
 Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Black Ash</u>
Diameter	<u>10"</u>	<u>14"</u>
Bearing	<u>N 51 1/2° E</u>	<u>N 72 1/4° W</u>
Distance	<u>25 links</u>	<u>155 links</u>

Evidence of Subsequent Corner Restoration

Year of search 11/1931 By P. Zeluyhoff, Estimator, CCC  
 Location filed: USFS Form 874-9  
 Monument: Found 1. pipe with brass cap  
 up 6" in good condition and witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Maple</u>	_____
Diameter	<u>9"</u>	_____
Bearing	<u>N 42 1/4° E</u>	_____
Distance	<u>15'</u>	_____

Subsequent Corner Restoration

Year surveyed 4/1964 By W.H. Okerman, LS 6807  
 Location filed: USFS Book 2, page 1  
 Monument: Found 2" iron post with brass cap  
 and witnessed as follows.  
 17" Black Ash, N 72° W, 102.30'(1930)  
 6" Maple, N 82° W, 24.2' scribed  
 8" Birch, North, 18.4' scribed  
 6" Cedar Post, N 22° E, 2.0' 54-4 sign


Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
 Location filed: \_\_\_\_\_  
 Monument: \_\_\_\_\_

Index No. 211

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
5114 33 Corner common to sections 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1871  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	Bearing	Trees
<u>Sugar</u>	<u>8"</u>	<u>Spruce</u>
<u>8"</u>	<u>N18W</u>	<u>8"</u>
<u>19LKS</u>	<u>N75E</u>	<u>25LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO  
Location filed Sec. of State  
Monument Set 2x36" l.p. willow brass cap SC  
114 533  
1930

Evidence of Subsequent Corner Restoration

Year of search 1964 By William Okerman  
Found GLO monument in good condition.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>10"</u>	<u>N51 1/2 E</u>	<u>25 LKS</u>
<u>Bk Ash</u>	<u>14"</u>	<u>N72 1/4 W</u>	<u>155 LKS</u>

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Maple</u>	<u>6"</u>	<u>N82 W</u>	<u>24.2'</u>
<u>Birch</u>	<u>8"</u>	<u>North</u>	<u>18.4'</u>
<u>Cedar Post</u>	<u>6"</u>	<u>N82 E</u>	<u>2.0'</u>

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
CERTIFICATE - BILL OKERMAN - 1964

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_