


T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

SE 33 Corner common to sections 33, 34 and 4-144-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species	<u>Sugar</u>	<u>Ironwood</u>
Diameter	<u>7"</u>	<u>7"</u>
Bearing	<u>N 48° W</u>	<u>N 48° E</u>
Distance	<u>11 links</u>	<u>16 links</u>

Original Bearing Trees Found

Species	_____	_____
Diameter	_____	_____
Bearing	_____	_____
Distance	_____	_____

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, U.S. Surveyor, GLO
 Location filed: MN Historical Society, Notes page 11
 Monument: Set 2"x 3' iron pipe with brass cap SC
 at proportionate distance, no evidence of T145N | R30W
 original position, new witnesses as follows. S 33 | S 34
1930
 NE cor. Sec. 4-144-30 is N 89°31' E, 38.55 Chains(2544.30')
 Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>
Diameter	<u>8"</u>	<u>8"</u>
Bearing	<u>N 11 3/4° E</u>	<u>N 35 3/4° W</u>
Distance	<u>86 links</u>	<u>70 links</u>

Evidence of Subsequent Corner Restoration

Year of search 11/1934 By P. Zeluyhoff, Estimator, CCC
 Location filed: USFS Form 874-9
 Monument: Found iron pipe
 in good condition and witnesses as follow.

Bearing Trees, Reference Objects

Species	<u>Maple</u>	<u>Maple</u>
Diameter	<u>8"</u>	<u>7"</u>
Bearing	<u>N 5° E</u>	<u>N 43° W</u>
Distance	<u>142 links</u>	<u>70 links</u>

Subsequent Corner Restoration

Year surveyed 4/1964 By W.H. Okerman, LS 6807
 Location filed: USFS Book 2, page 2
 Monument: Found 2" iron post with brass cap
 falls in restricted fallout research area and witnessed.
 12" Maple, N 12° E, 56.8'(1930) fallout research apparatus
 9" Maple, N 36° W, 46.2'(1930) high voltage box attached
 10" Maple, N 69° W, 35.0' scribed
 11" Oak, N 14° E, 23.15' scribed
 8" Oak, N 61° E, 14.2' FS 54-4 sign

5/1991, G. Brama, USFS
 USFS Book 2, page 2
 Found 2" iron post with brass cap, up 6", 367', S. of FR #2932
 and witnesses as follows.
 14" Maple, N 12° E, 56.8'(1930)
 13" Maple, N 36° W, 46.2'(1930)
 12" Maple, N 69° W, 35.0'(1964)
 17" Red Oak, N 14° E, 23.15'(1964)
 Steel Sign Post, South, 3'
 10" Red Oak, North, 367' FSLP N. side of FS #2932

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
 Location filed: _____
 Monument: _____

