

T. 145 R. 30 M. 5th Coordinates: X _____ Y _____

SE 34 Corner common to sections 34, 35 and 3-144-30



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____
Resurvey notes page 10

Bearing Trees

| | | |
|----------|---------------------|----------------|
| Species | <u>Yellow Birch</u> | <u>Sugar</u> |
| Diameter | <u>8"</u> | <u>9"</u> |
| Bearing | <u>N 55° E</u> | <u>N 78° W</u> |
| Distance | <u>17 links</u> | <u>5 links</u> |

Original Bearing Trees Found

| | | |
|----------|-------------------|-----------------|
| Species | <u>Birch stub</u> | <u>Maple</u> |
| Diameter | <u>12"</u> | <u>stump</u> |
| Bearing | <u>N 55° E</u> | <u>N 78° W</u> |
| Distance | <u>17 links</u> | <u>17 links</u> |

Subsequent Corner Restoration

Year surveyed 5/1930 By H.D. Craig, U.S. Surveyor, GLO
Location filed: MN Historical Society, Notes page 9
Monument: Set 2"x 3' iron pipe with brass cap from remains of original witnesses, up 6" and new witnesses as follows.
SC T145N | R30W
S 34 | S 35
1930

Evidence of Subsequent Corner Restoration

Year of search 7/1934 By D.B. Rose, Compassman, CCC
Location filed: USFS Form 874-9
Monument: Found Brass capped pipe up 4", in good condition and witnesses as follow.

Bearing Trees, Reference Objects

| | | |
|----------|-----------------|--------------------|
| Species | <u>Birch</u> | <u>White Pine</u> |
| Diameter | <u>18"</u> | <u>26"</u> |
| Bearing | <u>N 70° E</u> | <u>N 56 1/2° W</u> |
| Distance | <u>42 links</u> | <u>108 links</u> |

Bearing Trees, Reference Objects

| | | | |
|----------|----------------------|-------------------|---------------------|
| Species | <u>White Pine</u> | <u>Dead Birch</u> | <u>Yellow Birch</u> |
| Diameter | <u>26"</u> | <u>12"</u> | <u>16"</u> |
| Bearing | <u>N 54° W</u> | <u>N 61° E</u> | <u>N 87° E</u> |
| Distance | <u>106 1/4 links</u> | <u>17 links</u> | <u>42 links</u> |

Subsequent Corner Restoration

Year surveyed 4/1964 By W.H. Okerman, LS 6807
Location filed: USFS Book 2, page 4
Monument: Found 1" iron pipe with brass cap and witnesses as follows.
18" Birch, N 70° E, 27.7'(1930) Dead, scribe visible
White Pine, N 56° W, 71.3'(1930) stump
12" Maple, N 51° E, 33.25' scribed
6" Maple, N 77° W, 19.15' scribed
3" Maple, N 86° E, 8.1' FS 54-4 sign


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. 217

CASS COUNTY LAND CORNER RECORD

T. 145 R. 30 M. 5TH Coordinates: X _____ Y _____
SE34 Corner common to sections 34, 35



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

| | | | | | |
|----------|-----------------|--------------|-------|--|--|
| | | Bearing | Trees | | |
| Species | <u>Y. Birch</u> | <u>Sugar</u> | | | |
| Diameter | <u>8"</u> | <u>9"</u> | | | |
| Bearing | <u>N55E</u> | <u>N78W</u> | | | |
| Distance | <u>17LKS</u> | <u>5LKS</u> | | | |

Original Bearing Trees Found

| | | | |
|----------|-------|-------|-------|
| Species | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1930 By GLO
 Location filed Sec. of State
 Monument Find stumps of both B.T.S. Set at 36" 1. P.W. / brass cap
SC
N 89-45 W from N 1/4 S3 T145N / R30W
534 / 535

Evidence of Subsequent Corner Restoration

Year of search 1964 By William Okerman
Found GLO monument in good condition.

Bearing Trees, Reference Objects 1930

| | | | |
|----------|---------------|------------------|--|
| Species | <u>Birch</u> | <u>wilow</u> | |
| Diameter | <u>18"</u> | <u>26"</u> | |
| Bearing | <u>N70E</u> | <u>N56 1/2 W</u> | |
| Distance | <u>42 LKS</u> | <u>108 LKS</u> | |

Bearing Trees, Reference Objects

| | | | |
|---------------|---------------|--------------|--|
| <u>Maple</u> | <u>Maple</u> | <u>Maple</u> | |
| <u>12"</u> | <u>6"</u> | <u>3"</u> | |
| <u>N51E</u> | <u>N77W</u> | <u>N86E</u> | |
| <u>33.25'</u> | <u>19.15'</u> | <u>8.1'</u> | |

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - BILL OKERMAN - 1964

Remonumentation certificate prepared _____ By _____
Filed at _____ Date _____