


T. 145 R. 31 M. 5TH Coordinates: X _____ Y _____

M.C.# 24 Corner common to sections 3



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument Post

Bearing Trees

Species	<u>Tam</u>	<u>Tam</u>	
Diameter	<u>5"</u>	<u>5"</u>	
Bearing	<u>N11E</u>	<u>S23E</u>	
Distance	<u>40 LKS</u>	<u>42 LKS</u>	

Original Evidence Found

Year of search 1917 By C. Spencer
Monument found _____

Original Bearing Trees Found

Species	<u>Tam</u>	<u>Tam</u>	
Diameter			
Bearing	<u>N11°E</u>	<u>S23°E</u>	
Distance	<u>26.4'</u>	<u>27.7'</u>	

Subsequent Corner Restoration

Year surveyed AUG. 1922 By E.B. HIRST
Location filed CUBO BOOK 126, PAGE 3 (ME)
Monument FOUND NE U.S. BT - TAMCK 5" N 11°E 26.4' AND GOV'S STAKE BURIED IN MOSS. SET 7' 4" x 4" JACK PINE POST 5 1/2' INTO SWAMP NEEN INTO SAND BOTTOM

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Evidence of Subsequent Corner Restoration

Year of search 1917 By C.C. SPENCER
Beltrami Co. RB A, P. 167 & RB C, P. B FB 170383, Set Gas pipe 1 1/4 x 20"

Bearing Trees, Reference Objects

<u>Tam</u>	<u>Tam</u>		
<u>5"</u>	<u>4"</u>		
<u>N 40° E</u>	<u>N 20° E</u>		
<u>59.0'</u>	<u>48.7'</u>		

A-13, 14

Subsequent Corner Restoration

Year surveyed 1918 By C.C. Spencer
Location filed Beltrami Co.
Monument Found Gas pipe & BT's set by ME on road survey.

1932 H. Garg, GLO Fd 1 1/4 Dia galvanized iron pipe in concrete and witnessed.

Tam 5" N 5 1/2° E 75 lks = 49.5'
N. Pine 24' S 0° 15' E 626 lks = 413.16'

2006 Murray #15483 found iron pipe in concrete.

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____