


Index No. A 15

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X _____ Y _____
N143 Corner common to sections 3



O = Corner

EXISTING SURVEYS

Original Government Survey
Year surveyed 1875
Original monument Post

Original Evidence Found
Year of search 8/1922 By HARST
Monument found 1" I.M.

Bearing Trees	
Species <u>W. oak</u> <u>Aspen</u>	_____
Diameter <u>10"</u> <u>7"</u>	_____
Bearing <u>N37W</u> <u>Aspen</u>	_____
Distance <u>85 LKS</u> <u>105 LKS</u>	_____

Original Bearing Trees Found	
Species <u>OAK STUMP</u>	_____
Diameter <u>10"</u>	_____
Bearing <u>√3</u>	_____
Distance <u>√3</u>	_____

CURR BOOK 136, PAGE 5 (M/E)

Subsequent Corner Restoration
Year surveyed 1964 By DNR-Engineering
Location filed Map notes in file
Monument Found J.P. Found by Beltrami Co.
Engineer Bit 45' SSW

Evidence of Subsequent Corner Restoration
Year of search 1917 By CC Spencer
Beltrami Co. RB A, p.167, RB C, p.18
FB 170383, Found Oak BT, drove
3/4 x 48" Gas Pipe.

Bearing Trees, Reference Objects	
Species _____	_____
Diameter _____	_____
Bearing _____	_____
Distance _____	_____

Bearing Trees, Reference Objects	
<u>Oak</u>	<u>Old Elm</u>
<u>7"</u>	<u>7"</u>
<u>S</u>	<u>S30E</u>
<u>26.0</u>	<u>58.0</u>

A-15 Subsequent Corner Restoration
Year surveyed 1961 By A.L. Byc
Location filed Beltrami Co.
Monument Found iron pipe and BT's
as follows:
Elm 7" S30E 58.0
Oak 7" SW 26.0

Evidence of Subsequent Corner Restoration Found
Year of search _____ By _____

1987 OKerman Beltrami Co. FB
50, p.11, Fd CC Spencer 3/4" x 48"
gas pipe perpetuation of
original corner. Oak & Elm BT
in place Oak is S45°W not South
7/2006 - CCSO Found 1" ODIP on
fence line and located with
GPS.