


T. 145 R. 31 M. 5th Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_

MC #13 Corner common to sections 13 and 18-145-30



13

● = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search 1900 by COE  
Monument found \_\_\_\_\_

Lake Winnibigoshish Map

Bearing Trees

Species	<u>White Oak</u>	<u>Poplar</u>	_____
Diameter	<u>10"</u>	<u>8"</u>	_____
Bearing	<u>N 85° E</u>	<u>N 1° W</u>	_____
Distance	<u>40 links</u>	<u>36 links</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1900 By T.M. Fowble, COE  
Location filed: Lake Winnibigoshish Reservoirs Map  
Monument:  
Indicates original corner recovered.

Evidence of Subsequent Corner Restoration

Year of search 6/1933 By W.W. Bandy, Surveyor  
Location filed: Resurvey Notes T145N  
Monument: Set 6" concrete cylinder w/ brass tablet R31W | R30W  
at proportionate position. S 13 | S 18  
MC  
1933

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

Species	<u>Burr Oak</u>	<u>Burr Oak</u>	_____
Diameter	<u>4"</u>	<u>5"</u>	_____
Bearing	<u>S 45° E</u>	<u>N 35 1/2° W</u>	_____
Distance	<u>38 links</u>	<u>23 links</u>	_____

Subsequent Corner Restoration

Year surveyed 1/1934 By J.A. Gjelhaug, CCC  
Location filed: 145-30 Form 874  
Monument: Found Brass capped cement  
up 5", at N. shore Pike Bay and witnesses.  
5" W. Oak, N 34° W, 22 1/2 links (1933)  
4" W. Oak, S 47° E, 37 1/2 links (1933)

Evidence of Subsequent Corner Restoration Found


Year of search \_\_\_\_\_ By \_\_\_\_\_  
Location filed: \_\_\_\_\_  
Monument: \_\_\_\_\_

3/1996, R. Main, USFS  
USFS 145-30, Book 1, page 20  
Found GLO brass cap in concrete, 30'+/-, N. of shore line,  
200'+/-, W. of lease Cabin and witnesses.  
11" W. Oak, N 28° W, 14.99'(1933) to spike  
6" W. Oak, N 47° E, 14.85' to spike  
Steel Sign Post, North, 2.25'

Index No. L-m 25

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC # 13 Corner common to sections 13 AND 18-145-30



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument Post

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Bearing Trees  
Species Poplar W. oak  
Diameter 8" 10"  
Bearing N1W N 85E  
Distance 36 LKS 40 LKS

Original Bearing Trees Found

Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Subsequent Corner Restoration

Year surveyed 1933 By GLO  
Location filed Sec. of state  
Monument Set concrete mon 24" long 6" Dia w/ brass cap  
T145N  
R31W / R30W  
S13 / S18

Evidence of Subsequent Corner Restoration

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Bearing Trees, Reference Objects <sup>MC</sup> 1933

Species Br. oak Br. oak  
Diameter 4" 5"  
Bearing S45E N35 1/2 W  
Distance 38 LKS 23 LKS

Bearing Trees, Reference Objects

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Remonumentation certificate prepared \_\_\_\_\_ By \_\_\_\_\_  
Filed at \_\_\_\_\_ Date \_\_\_\_\_