


T. 145 R. 31 M. 574 Coordinates: X _____ Y _____
N14 19 Corner common to sections 18, 19



EXISTING SURVEYS

Original Government Survey

Year surveyed 1875
Original monument bst

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>J. Pine</u>	<u>J. Pine</u>	
<u>12"</u>	<u>12"</u>	
<u>S32W</u>	<u>N67E</u>	
<u>56 LKs</u>	<u>53 LKs</u>	

Species	Bearing	Trees
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration

Year of search 1993 10-28 By Robert Murray
Placed MoDOT cast iron monument.
4-26-94 Cert. Filed by Robert Murray,
RLS 15483, DOC. # 357127.

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Norway</u>	<u>10"</u>	<u>N26E</u>	<u>68.91</u>
<u>Norway</u>	<u>10"</u>	<u>N42W</u>	<u>94.82</u>
<u>Jack Pine</u>	<u>5"</u>	<u>S26W</u>	<u>57.67</u>

N-3

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search 2000 DEC. By CCSO
Find. in place; CIM, flush w/ bit. Located
1.3' South of E.C.R. 22. Located 1993 B.T.'s
set by R. Murray (RLS 15483)

REF. TIES:

<u>10" N. Pine</u>	<u>N 42° W</u>	<u>94.82' (found B.T.)</u>
<u>(T.F.) 10" N. Pine</u>	<u>N 26° E</u>	<u>68.91' " "</u>
<u>5" J. Pine</u>	<u>S 26° W</u>	<u>57.67' " "</u>

* distances from corner are measured to scribes in trees.