


T. 145 R. 31 M. 5th Coordinates: X _____ Y _____
S 1/4 36 Corner common to sections 36 and 1-144-31



EXISTING SURVEYS

Original Government Survey

Year surveyed 1871
Original monument Post

Original Evidence Found

Year of search 1930 by Craig
Monument found _____
T144N R31W notes page 8

Bearing Trees

Species	<u>Yellow Pine</u>	<u>Yellow Pine</u>
Diameter	<u>30"</u>	<u>30"</u>
Bearing	<u>N 8° E</u>	<u>N 50° W</u>
Distance	<u>151 links</u>	<u>29 links</u>

Original Bearing Trees Found

Species	<u>N. Pine stp</u>	<u>N. Pine stp</u>
Diameter	<u>32"</u>	<u>28"</u>
Bearing	<u>N 8°30' E</u>	<u>N 50° W</u>
Distance	<u>151 links</u>	<u>29 links</u>

Subsequent Corner Restoration

Year surveyed 6/2014 By H.D. Craig, U.S. Surveyor, GLO
Location filed: MN Hist. Society, T144N R31W notes page 8
Monument: Set 1"x 3' iron pipe with brass cap from remains of GLO witnesses and marked new witnesses as follows. S.C. 1/4 S36 1930

Evidence of Subsequent Corner Restoration

Year of search 12/1931 By J. Kyes, Estimator, CCC
Location filed: USFS Form 874-9
Monument: Iron pipe up 8" in good condition. On road in narrow neck of land between Twin Lakes. Corner posted at road. Line was blazed. Cutface chopped on Norway facing corner.

Bearing Trees, Reference Objects

Species	<u>Norway Pine</u>	<u>Jack Pine</u>
Diameter	<u>17"</u>	<u>17"</u>
Bearing	<u>N 86°30' E</u>	<u>N 72°45' W</u>
Distance	<u>73 links</u>	<u>153 links</u>

Bearing Trees, Reference Objects

Species	<u>J. Pine</u>	<u>N. Pine</u>
Diameter	<u>14"</u>	<u>15"</u>
Bearing	<u>S 69° W</u>	<u>N 8° E</u>
Distance	<u>100'</u>	<u>45'</u>

Subsequent Corner Restoration

Year surveyed 7/1969 By W.H. Okerman, LS 6807
Location filed: T145N R31W Field Book 1, page 7
Monument: Found 1" brass capped iron pipe and remains of Original witness stumps, 25'+/-, W. of old road, 15'+/-, S. of pipeline clearing and witnessed as follows.
9" Norway Pine, N 73° W, 78.5' scribed
9" Jack Pine, N 25° W, 170.85' scribed
6" Red Oak, N 12° E, 109.05' scribed
4" Cedar Post, South, 3.65' F.S. 54-4 sign


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed: _____
Monument: _____

Index No. Z 23

CASS COUNTY LAND CORNER RECORD

T. 145 R. 31 M. 5th Coordinates: X _____ Y _____
514 Corner common to sections 36



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees
<u>Y. Pine</u>	<u>N 50 W</u>	<u>Y. Pine</u>
<u>30"</u>		<u>30"</u>
<u>151 LKS</u>		<u>29 LKS</u>

Species	Bearing	Distance
_____	_____	_____
_____	_____	_____
_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1930 By GLO
Location filed Sec. of State
Monument End steps of both B.T.S set N36" N.W. 1/4 Sec 5C
1/4 536
1930

Evidence of Subsequent Corner Restoration

Year of search 1969 By William Okerman
Found GLO monument in good condition.

Species	Bearing	Trees	Reference Objects
<u>N. Pine</u>	<u>17"</u>	<u>J. Pine</u>	<u>17"</u>
<u>N86-30E</u>		<u>N72-45W</u>	
<u>73 LKS</u>		<u>153 LKS</u>	

Species	Bearing	Distance	Reference Objects
<u>N. Pine</u>	<u>9"</u>	<u>N73W</u>	<u>78.50'</u>
<u>J. Pine</u>	<u>9"</u>	<u>N25W</u>	<u>170.85'</u>
<u>R. Oak</u>	<u>6"</u>	<u>N12E</u>	<u>109.05'</u>
<u>Cedar post</u>			<u>4x4x72"</u>
			<u>South</u>
			<u>3.65'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed _____
Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Bill Okerman - 1969 - recorded 1971

Remuneration certificate prepared _____ By _____
Filed at _____ Date _____