


Index No. _____

CASS COUNTY LAND CORNER RECORD

T. _____ R. _____ M. _____ Coordinates: X _____ Y _____

Corner common to sections _____



= Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed _____
Original monument _____

Original Evidence Found

Year of search _____ by _____
Monument found _____

Bearing Trees

Species _____
Diameter _____
Bearing _____
Distance _____

Original Bearing Trees Found

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:

Evidence of Subsequent Corner Restoration

Year of search _____ By _____
Location filed:
Monument:

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Bearing Trees, Reference Objects

Species _____
Diameter _____
Bearing _____
Distance _____

Subsequent Corner Restoration

Year surveyed _____ By _____
Location filed:
Monument:


Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Location filed:
Monument:

Index No. V21

CASS COUNTY LAND CORNER RECORD

T. 146 R. 27 M. 574 Coordinates: X _____ Y _____
NE 35 Corner common to sections 25, 26, 35, 36



EXISTING SURVEYS

Original Government Survey

Year surveyed 1874
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Species	Bearing	Trees	Distance
<u>N. Pine</u>	<u>N. Pine</u>	<u>N. Pine</u>	<u>J. Pine</u>
<u>13"</u>	<u>14"</u>	<u>8"</u>	<u>8"</u>
<u>S17E</u>	<u>S7W</u>	<u>N31W</u>	<u>N54W</u>
<u>85LKS</u>	<u>87LKS</u>	<u>51LKS</u>	<u>74LKS</u>

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1969? By Co HWY Dept
Location filed Co RD # 9
Monument Brass cap monument in concrete

Evidence of Subsequent Corner Restoration

Year of search 1982 By Ken Whitehorn - USFS
Corner Certificate - Doc # 276896
End 1929 Corps of Engineers concrete monument w/ brass disc. and 3 orig B.T.S

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>N. Pine</u>	<u>25"</u>	<u>N33-12E</u>	<u>33.66'</u>
<u>w. oak</u>	<u>10"</u>	<u>N49-41E</u>	<u>20.00'</u>
<u>N. Pine</u>	<u>23"</u>	<u>S17-41E</u>	<u>56.10'</u>
<u>N. Pine</u>	<u>24"</u>	<u>S6-25W</u>	<u>57.42'</u>
<u>N. Pine</u>	<u>23"</u>	<u>S83-51W</u>	<u>54.08'</u>
		(orig)	(orig)
		(orig)	(orig)
		(orig)	(orig)

Subsequent Corner Restoration

Year surveyed OCT 1926 By R.A. DANMS, ENGR
Location filed CASS Co. SURV. BOOK 156 PG 19
Monument CASS S.A.R. #9 TRANSIT NOTES
194' S. TO COR. 25, 26, 35 & 36

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Ken Whitehorn - USFS - 1983

Remonumentation certificate prepared _____

By _____

Filed at _____

Date _____