

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

25

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 24 & 25 W 4th Mer.

1/4 Corner common to Sections 25, and 30


Corner consists of a None (not) in place State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Pine Stump

Diameter

Bearing N 85° W

Distance 22.162

Do you believe this to be a genuine Land Office Corner? No

If not, why? Does not match with G.H.O. notes so believe it was set by County Surveyor.

Arthur J. Johnson

(Signature)


Special Foreman

(Title)

2/16/90

(Date)

(Make sketch of topography near Corner)



T. 58 N. R. 29 E. 25 W. 47 N. Mer.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.

This Corner is 7 chains North of  
 Cutaway Road.

U. S. Department of Agriculture  
FOREST SERVICE

T-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 29&25W 9th Mer.

1/4 Corner common to Sections  
25, and 30

Corner consists of a None (not) in place  
State condition

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/4</u> <u>5.25</u>			
<u>BT</u>			

Species Pine Stamp

Diameter \_\_\_\_\_

Bearing N 85° W

Distance 521ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Does not match with  
E. L. O. Notes so believe it was  
set by County Surveyor.

Arthur J. Johnson

(Signature)

Squad Foreman

(Title)

2/16/20  
(Date)

This corner is 7 chains North of Cutaway Road.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 58N R. 1425W 4TH Mer.

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

T-25

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 58N R24+25W 9th Mer.

1/4 Corner common to Sections  
25, and 30

Corner consists of a None (none) in place  
State condition

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_  
Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 525			
BT			


Species Pine Stump  
Diameter \_\_\_\_\_  
Bearing N 85° W  
Distance 521ks

Do you believe this to be a genuine Land Office Corner? NO  
If not, why? Does not match with B.L.O. notes I believe it was set by County Surveyor

Arthur T. Johnson  
(Signature)  
Squad Foreman  
(Title)

2/16/30  
(Date)

(Make sketch of topography near Corner)



T. 58 N. R. 19 + 25 W. 4th Mer.

Metal Location Poster is on a  
 tree inches diameter, on the  
 side of  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.

This Corner is 4 chains North of  
 Cutaway Road.