

U. S. Department of Agriculture

FOREST SERVICE

X, 4-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 24W 25W 4th Mer.

Meander Corner common to Sections 31, and 36

Corner consists of a None (not) in place


State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5.31

5.36

B.T.

BT

Species Ash Stump Ash Stump

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Records show it was set by County

Surveyor.

Arthur J. Johnson

(Signature)

Squad Foreman


(Title)

2/15/40

(Date)

(Make sketch of topography near Corner)

T. 58 N R. 29 T. 26 N Mer.



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

Could not locate Poster check distance

and bearing of B.T.'s because the water

level of Hanson hole has raised until

spot is flooded

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N R. 24 W 25 W 4th Mer.

Meander Corner common to sections

31, and 36

Corner consists of a None (not) in place


State condition

Dimensions above ground inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5.36

3.31

B.T.

B.T.

Species Ash Stump Ash Stump

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? NO

If not, why? B.T.s do not check with original notes.

Arthur J. Johnson

(Signature)

Special Foreman

(Title)


2/15/90

(Date)

X-4-Y-25

Corner again.  
 Could set a Post near the  
 having a diameter of 8.5  
 Water level of stream on high tides  
 raised until Post is covered with  
 Water.

Metal Location Poster is on a  
 tree inches diameter, on the  
 side of  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST X-725

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 29+25W 4th Mer.

Meander Corner common to Sections

31, and 36

Corner consists of a None (not) in place


State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5.31	5.36		
B.T.	B.T.		

Species Ash Stump Ash Stump

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? B.T.'s do not check with G.L.O. notes.

Arthur T. Johnson

(Signature)

Special Foreman


(Title)

2/15/90

(Date)

Corner again.  
 Could not locate Post or check distance  
 & bearing to B.T. because water level of  
 Hanson Lake has raised until spot is  
 flooded.

Metal Location Poster is on a  
 tree inches diameter, on the  
 side of  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 58N R. 29E 25W 9th Mer.